

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21008179/AGUF3N2**Date:** 28/09/2021**REFERENCE**

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001152370

Claimant Vehicle No : SLR1351T**Insured Vehicle No :** SLF390A

Date of Loss: 02/08/2021

Nature of Claim: TP Claim No: 260725

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLR1351T**

Make & Model: OPEL ASTRA ST, 1.0 AT (A)

Engine No: B1170257HRXX0241

Reg. Date: 01/08/2017 (Man. Year: 2017)

Chassis No: W0LBE8EA3H8057878

Colour: Grey

Odometer: 61607 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size: 225/45R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,275.30	2,475.20	800.10	24.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	480.00	570.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,325.30	2,955.20	1,370.10	31.68
+ GST 7.00/7.00% (S\$)	302.77	206.86	95.91	31.68
Nett Amount (S\$)	4,628.07	3,162.06	1,466.01	31.68

INSPECTION

Date of Assignment: 04/08/2021

Date Inspected: 10/08/2021 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** Tan Hui Zhen*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Sep 2021)	
Parts:	N/A	OPEL ASTRA ST 1.0 AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR1351T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,740.00 FL	*1,740.00 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Not Necessary	114.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR-RH	Not Necessary	65.00 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	710.00 FL	*- FL
5	1		*TAIL LAMP-RH	Cracked	738.00 FL	*738.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
7	1		*REVERSE SENSOR	Damaged	195.00 FS	*195.00 FS
					Sub Total (\$\$)	3,612.00 2,723.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	336.70 247.80
					Total Parts (\$\$)	3,275.30 2,475.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	400.00	200.00
2	TO PUTTY AND SPRAY UP PAINT WORKS	New	500.00	200.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			1,050.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >