

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008181/TQCN2**Date:** 31/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004932000

Claimant Vehicle No : SLX7886X **Insured Vehicle No :** SMP7230T

Date of Loss: 29/07/2021 Nature of Claim: TP Claim No: SNM21D204242/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX7886X**

Make & Model: MERCEDES-BENZ A180, 1.6 (A) Engine No: 27091031530862

Reg. Date: 11/04/2018 (Man. Year: 2017) Chassis No: WDD1760422J725109

Colour: Red Odometer: 40343 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,961.70	6,773.54	6,188.16	47.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,950.00	2,050.00	3,900.00	65.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,911.70	8,823.54	10,088.16	53.34
Approved Total (Overridden) (\$\$)		7,000.00		
(\$\$)	18,911.70	7,000.00	11,911.70	62.99
+ GST 7.00/7.00% (\$\$)	1,323.82	490.00	833.82	62.99
Nett Amount (\$\$)	20,235.52	7,490.00	12,745.52	62.99

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 04/08/2021 Inspected At: 56 LOYANG WAY,
#04-04 LOYANG ENTERPRISE BUILDING
REPAIRER: AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	MERCEDES-BENZ A180 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX7886X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,023.00 FL	*1,305.00 FL
2	1		*TAILGATE WINDSCREEN W MOULDING	Necessary	564.00 FL	*141.60 FL
3	1		*TAILGATE LOGO-MERCEDES	Necessary	51.00 FL	*51.00 FL
4	1		*TAILGATE EMBLEM-A180	Necessary	82.00 FL	*82.00 FL
5	1		*TAILGATE EMBLEM-AMG	Necessary	79.00 FL	*79.00 FL
6	1		*TAILGATE HANDLE SWITCH	Not Necessary	175.00 FL	*- FL
7	1		*TAILGATE LOCK	Bent	287.00 FL	*274.00 FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	38.00 FL	*- FL
9	1		*TAILGATE INNER TRIM	Deformed	152.00 FL	*152.00 FL
10	2		*TAILGATE HINGE	Not Necessary	184.00 FL	*- FL
11	2		*TAILGATE DAMPER	Not Necessary	60.00 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Deformed	235.00 FL	*168.00 FL
13	2		*TAIL LAMP L+R	Cracked	1,370.00 FL	*1,250.00 FL
14	2		*TAIL LAMP PANEL L+R	Not Necessary	140.00 FL	*- FL
15	1		*REAR BUMPER	Deformed	1,285.00 FL	*1,150.00 FL
16	2		*REAR BUMPER REVERSE SENSOR	Not Working	572.00 FL	*350.00 FL
17	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	137.00 FL	*- FL
18	1		*REAR BUMPER TOW COVER	Deformed	85.00 FL	*85.00 FL
19	1		*REAR BUMPER LOWER	Deformed	250.00 FL	*250.00 FL
20	1		*REAR BUMPER RETAINER L+R	N/s Deformed/O/s Not Necessary	124.00 FL	*62.00 FL
21	1		*REAR BUMPER CENTER BRACKET	Not Necessary	109.00 FL	*- FL
22	1		*REAR BUMPER REINFORCEMENT BAR	Bent	510.00 FL	*510.00 FL
23	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*REAR BUMPER UNDERCOVER (NPA)	Not Necessary	0.00 FL	*- FL
25	2		*REAR FENDER INNER TRIM L+R	Not Necessary	670.00 FL	*- FL
26	2		*REAR FENDER COWLING L+R	Torn	320.00 FL	*320.00 FL
27	1		*END PANEL	Bent	1,050.00 FL	*765.00 FL
28	1		*END PANEL TOP GARNISH	Deformed	86.00 FL	*86.00 FL
29	1		*FLOOR PANEL (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*FLOOR PANEL TOP BOARD	Not Necessary	820.00 FL	*- FL
31	1		*FLOOR PANEL ACCESSORIES TRAY	Not Necessary	160.00 FL	*- FL
32	1		*EXHAUST PIPE	Not Necessary	1,055.00 FL	*- FL
33	1		*EXHAUST HEAT SHIELD	Bent	140.00 FL	*140.00 FL
34	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
36	1		*REAR NUMBER PLATE	Cut	120.00 FS	*45.00 FS
37	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
40	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
41	1		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
42	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
43	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

5/31/22, 10:07 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FLOOR PANEL SEALANT	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	14,243.00
					7,495.60	
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,281.30
						722.06
					Total Parts (\$\$)	12,961.70
						6,773.54
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	700.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	80.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
8	TO RNR UNDERCARRIAGE	New	250.00	0.00
9	TO CHECK WATER LEAK	New	150.00	30.00
10	TO RNR FUEL TANK	New	250.00	0.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	200.00
12	TO RNR REAR TAILGATE MECHANISM	New	300.00	60.00
13	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
14	TO PERFORM RUST PROOFING	New	200.00	40.00
Gross Labour Cost (\$\$)			5,950.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >