



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108326

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 02/12/2021
Reference CC4/FCI21008186/Gga3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 3363E
Insured Veh. SBS 3352R
Claim No. D21002227MFBP/1
Policy No. D-21097502MFBP
Accident Date 17/07/2021
Inspection Date 04/08/2021

Description	Total
Survey Inspection	277.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	277.00
GST (7%)	19.39
Grand Total	296.39

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008186/Gga3q2	
			Date: 02/12/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3352R	Veh. Inspected	SMN 3363E	
Policy No.	D-21097502MFBP	Coverage (\$)	0.00	
Claim No.	D21002227MFBP/1	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	03/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE HYBRID 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72001839	Colour	BLACK	
Odometer	197893 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DUNLOP	6 mm	
L/H Front Tyre	185/60 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2021	Inspection Date	04/08/2021	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 3363E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	1,250.00	1,050.00
1	FRONT BUMPER SIDE RETAINER LH	BROKEN	18.70	18.70
1	FRONT BUMPER FOG LAMP COVER LH	NOT NECESSARY	165.00	-
1	HEADLAMP LH	NOT NECESSARY	950.00	-
1	HEADLAMP LOWER BRACKET LH	NOT NECESSARY	78.00	-
1	FRONT FENDER LH	BUCKLED	411.90	411.90
1	FRONT FENDER INNER SHIELD LH	DEFORMED	145.00	110.50
1	FRONT FENDER INNER EMBLEM LH	NECESSARY	42.00	42.00
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	456.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	398.00	-
1	FRONT KNUCKLE ARM BEARING LH	NOT NECESSARY	215.00	-
1	FRONT LOWER ARM LH	NOT NECESSARY	548.00	-
	LESS 20% DISCOUNT		-935.52	-326.62
			3,742.08	1,306.48
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NECESSARY	80.00	20.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	FRONT SPORTS RIM LH (SN)	CUT	600.00	250.00
			760.00	300.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL WIRING .		80.00	20.00
	REMOVE AND RENEW FRONT UNDERCARRIAGE.	NOT NECESSARY	400.00	-
	CONDUCT WHEEL ALIGNMENT.		150.00	60.00
	TO RESPRAY UNDERCOATING.		300.00	40.00
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	400.00
	PANEL BEATING ON AFFECTED AREAS .		800.00	300.00
			2,730.00	820.00
	GRAND TOTAL		7,232.08	2,426.48



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00
---	--	--	-----------------

Report Ref No. CC4/FCI21008186/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 3363E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 3363E

RE-INSPECTION

