



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4051U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	DENTED / BUCKLED	1,208.00	917.90
1	REAR BUMPER REFLECTOR (CONSISTENT)	SCRATCHED / CRACKED	539.00	125.80
1	REAR BUMPER RETAINER LH (CONSISTENT)	NECESSARY	128.00	128.00
1	REAR REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	659.00	-
1	REAR REINFORCEMENT SPONGE (CONSISTENT)	SERVICEABLE	198.00	-
1	REAR FENDER (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-683.00	-292.93
			2,049.00	878.77
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	60.00	60.00
			60.00	60.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF REAR REINFORCEMENT AND REAR FENDER.		500.00	200.00
	SPRAY PAINTING ON ACCIDENT AREAS .		600.00	220.00
	WIRING CHARGES.		100.00	10.00
	APPLY UNDERCOATING TO ABOVE AFFECTED AREAS .	NOT NECESSARY	220.00	-
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			1,540.00	430.00
	<b>GRAND TOTAL</b>		<b>3,649.00</b>	<b>1,368.77</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,000.00</b>

Report Ref No. CC4/ASM21008188/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.