3/30/23, 4:41 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21008204/EQCQ2

30/03/2023 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00053192100

Claimant Vehicle

GBG5746M

Insured

No:

Vehicle No:

YQ3729B

Date of Loss:

Nature of 29/07/2021 Claim:

TP

Claim SNM21D204284/C02/THAMYL No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBG5746M Reg No:

R06A2122947 Make & Model: SUZUKI EVERY, 658cc PA 660 (A) Engine No: Reg. Date: 30/08/2017 (Man. Year: 2017) Chassis No: DA17V820391 75615 km Colour: Black Odometer:

Engine Capacity: 658 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Engine Modification: Pre-accident Condition: Handbrake (Serviceable): Yes Nο

CONDITION OF TYRES

Front Tyre Size: 155 R12C Rear Tyre Size: 155 R12C Rear Left Side: APLUS 5 mm Front Left Side: APLUS 5 mm Front Right Side: APLUS 5 mm Rear Right Side: APLUS 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,703.00	942.15	760.85	44.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	810.00	1,440.00	64.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,953.00	1,752.15	2,200.85	55.68
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	3,953.00	1,400.00	2,553.00	64.58
+ GST 8.00/8.00% (S\$)	316.24	112.00	204.24	64.58
Nett Amount (S\$)	4,269.24	1,512.00	2,757.24	64.58

INSPECTION

Date of Assignment: 23/08/2021

Efficient Motor & Engineering Works Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang Enterprise Date Inspected: 02/11/2021 Inspected At: Building

Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Mar 2023)

Parts: N/A SUZUKI EVERY 658cc PA 660 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG5746M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,500.00 FL	*899.00 FL
2	1		*TAILGATE STICKER EVERY	Necessary	70.00 FL	*40.00 FL
3	2		*TAILGATE HINGE	Not Necessary	140.00 FL	*- FL
4	1		*TAILGATE EMBLEM	Necessary	70.00 FL	*40.00 FL
5	1		*70KM/H STICKER	Necessary	30.00 FS	*20.00 FS
6	1		*SEALANT	Necessary	80.00 FS	*40.00 FS
7	1	nort C=CnoNo	*PAN PACIFIC PLATE tt. L=ListItemDisc.	Necessary	80.00 FS	*50.00 FS
F-F18	anchise	рап. 5-5рске	u. L-Listitembisc.	Sub Total (S\$)	1,970.00	1,089.00
			- List Item Discount on L Items 15.00/15.00% (S\$)		267.00	146.85
				Total Parts (S\$)	1,703.00	942.15
			Report was unsi	ubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PANEL BEAT ON RH REAR PORTION AND TO REPLACE REAR DAMAGED PARTS	New	1,000.00	200.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	150.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	50.00	30.00
4	TO PUTTY ,SPRAY PAINTING REAR PORTIONS & OTHER AFFECTED AREAS	New	800.00	400.00
5	TO TRANSFER TAILGATE COMPONENTS TO NEW TAILGATE	New	100.00	30.00
6	TO REMOVE & REFIT REAR WINDSCREEN GLASS	New	150.00	120.00
	Gross Labou	2,250.00	810.00	
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >