

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21008207/VTF3E2**Date:** 12/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900016000
Claimant Vehicle No :	FBQ7512E	Insured Vehicle No :	SMH6376E
Date of Loss:	23/05/2021	Nature of Claim:	TP
		Claim No:	9769768358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ7512E	Engine No:	KF51E1018004
Make & Model:	HONDA ADV150, 149cc ABS CVT	Chassis No:	MH1KF5111KK019041
Reg. Date:	03/12/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80-14	Rear Tyre Size:	130/70-13
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/08/2021	
Date Inspected:	04/08/2021	Inspected At: Ss Motoring (HQ) 1084 SERANGOON ROAD Singapore 328186
Estimated Period of Repair:	3.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$10,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT WING MIRROR LH	Cut	0.00 F	*- F
3	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
6	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
7	1		*HAND BRAKE LEVER LH	Cut	0.00 F	*- F
8	1		*SIDE FAIRING LH	Cracked	0.00 F	*- F
9	1		*SIDE FAIRING TOP GARNISH	Cracked	0.00 F	*- F
10	1		*SIDE FAIRING INNER GARNISH LH	Cut	0.00 F	*- F
11	1		*FAIRING SHIELD	Cut	0.00 F	*- F
12	1		*REAR WHEEL SIDE COVER TOP	Cut	0.00 F	*- F
13	1		*REAR WHEEL SIDE COVER BOTTOM	Cut	0.00 F	*- F
14	1		*REAR FOOT REST LH	Bent	0.00 F	*- F
15	1		*REAR BOX	Cut	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >