

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008208/KVCN2**Date:** 31/08/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00005692000

**Claimant Vehicle
No :** SFC3209J**Insured
Vehicle No :** SMQ7625H

Date of Loss: 31/07/2021

Nature of Claim: TP

Claim
No: SNM21D204278/C02/TANKW**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SFC3209J**

Make & Model: MITSUBISHI LANCER, 2.0 L MIVEC (A)

Engine No: 4B11AN0540

Reg. Date: 03/10/2007 (Man. Year: 2007)

Chassis No: JMYSTCY4A8U000878

Colour: Metallic Black

Odometer: 291919 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18

Rear Tyre Size: 225/40ZR18

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,613.47	2,876.40	1,737.07	37.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	1,430.00	940.00	39.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,983.47	4,306.40	2,677.07	38.33
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	6,983.47	3,450.00	3,533.47	50.60
+ GST 7.00/7.00% (S\$)	488.84	241.50	247.34	50.60
Nett Amount (S\$)	7,472.31	3,691.50	3,780.81	50.60

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 04/08/2021 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 &
17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2021)
Parts:	143	mitsubishi LANCER 2.0 L MIVEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFC3209J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent/Warped	935.00 FL	*935.00 FL
2	10		*REAR DOOR TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
3	1		*ROCKER PANEL LH	Bent	652.00 FL	*652.00 FL
4	1		*REAR WHEEL BEARING	Not Necessary	453.00 FL	*- FL
5	1		*REAR BUMPER	Mtg Cracked	876.00 FL	*815.00 FL
6	14		*REAR BUMPER CLIPS	Necessary	42.00 FL	*42.00 FL
7	1		*REAR BUMPER CORNER RETAINER LH	Serviceable	20.70 FL	*- FL
8	1		*REAR DOOR WEATHERSTRIP (50%)	Cut	126.54 FS	*70.30 FS
9	1		*REAR WHEEL RIM	Dented	840.60 FS	*280.00 FS
10	1		*REAR DOOR VISOR	Necessary	180.00 FS	*60.00 FS
11	1		*REAR DOOR VISOR CHROME MOULDING	Not Necessary	120.00 FS	*- FS
12	1		*REAR DOOR INNER INSULATION	Not Necessary	150.00 FS	*- FS
13	1		*ROCKER PANEL TOP STEP SCUFF PLATE	Necessary	180.00 FS	*60.00 FS
14	1		*REAR TYRE (70%)	Cut	295.00 FS	*206.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,915.84	3,120.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	302.37	244.40
Total Parts (\$\$)	4,613.47	2,876.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/TRANSFER REAR DOOR FITTINGS/ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO SUPPLY REAR FENDER BODY SEALANT	New	60.00	30.00
3	TO REPLACE REAR WHEEL BEARING	New	100.00	0.00
4	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
5	TO CONDUCT HIGH SPEED BALANCING	New	80.00	20.00
6	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	100.00	60.00
7	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR FENDER,ROCKER INNER PANEL,FLOOR PANEL ETC.CNT,WELD ROCKER PANEL AND PART REPLACEMENT	New	900.00	600.00
8	TO RESPRAY AFFECTED AREAS	New	900.00	600.00
Gross Labour Cost (\$\$)			2,370.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >