

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008209/TQCM4**Date:** 31/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00090332000

Claimant Vehicle No : SMH3726Z **Insured Vehicle No :** YP8222T

Date of Loss: 02/08/2021 Nature of Claim: TP Claim No: SNM21D204306/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH3726Z**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHL9177

Reg. Date: 21/01/2019 (Man. Year: 2018) Chassis No: MMBSTA13AKH000618

Colour: Black Odometer: 35536 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,731.10	3,141.90	7,589.20	70.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	1,620.00	5,580.00	77.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,931.10	4,761.90	13,169.20	73.44
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	17,931.10	3,800.00	14,131.10	78.81
+ GST 7.00/7.00% (\$\$)	1,255.18	266.00	989.18	78.81
Nett Amount (\$\$)	19,186.28	4,066.00	15,120.28	78.81

INSPECTION

Date of Assignment: 04/08/2021

Date Inspected: 05/08/2021 Inspected At: 56 LOYANG WAY,
#04-04 LOYANG ENTERPRISE BUILDING
SINGAPORE 508775
REPAIRER : AP AUTOMOTIVE SERVICES PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2022)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH3726Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	952.00 FL	*828.00 FL
2	1		*BOOTLID LOGO - MITSUBISHI	Necessary	44.00 FL	*44.00 FL
3	1		*BOOTLID EMBLEM - ATTRAGE	Necessary	39.00 FL	*39.00 FL
4	1		*BOOTLID EMBLEM - MIVEC	Necessary	47.00 FL	*47.00 FL
5	1		*BOOTLID EMBLEM - C&C	Necessary	33.00 FL	*33.00 FL
6	1		*BOOTLID CHROME GARNISH	Not Necessary	332.00 FL	*- FL
7	2		*BOOTLID NUMBER PLATE LAMP L+R	Not Necessary	96.00 FL	*- FL
8	1		*BOOTLID LOCK CYLINDER	Not Necessary	76.00 FL	*- FL
9	1		*BOOTLID LOCK	Bent	298.00 FL	*139.00 FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	32.00 FL	*- FL
11	1		*BOOTLID INNER TRIM (NPA)	Not Necessary	-	-
12	2		*BOOTLID HINGE SET	Not Necessary	112.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Cut	183.00 FL	*155.00 FL
14	2		*TAIL LAMP L+R	Cracked	752.00 FL	*664.00 FL
15	2		*TAIL LAMP PANEL L+R	Not Necessary	150.00 FL	*- FL
16	1		*REAR BUMPER	Deformed	822.00 FL	*660.00 FL
17	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	50.00 FL	*- FL
18	2		*REAR BUMPER RETAINER L+R	Cracked	58.00 FL	*58.00 FL
19	1		*REAR BUMPER REINFORCEMENT BAR (NPA)	Not Necessary	-	-
20	2		*REAR BUMPER BRACKET L+R	Not Necessary	56.00 FL	*- FL
21	2		*REAR WINDSCREEN MOULDING	Not Necessary	136.00 FL	*- FL
22	2		*REAR FENDER L+R	Not Necessary	1,710.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM L+R	Not Necessary	326.00 FL	*- FL
24	2		*REAR FENDER COWLING L+R	Torn	352.00 FL	*76.00 FL
25	1		*END PANEL	Repair	452.00 FL	*- FL
26	1		*END PANEL TOP GANISH	Deformed	71.00 FL	*150.00 FL
27	1		*SPAREWHEEL PANEL	Repair	921.00 FL	*- FL
28	1		*SPAREWHEEL PANEL TOP BOARD	Cracked	198.00 FL	*198.00 FL
29	1		*EXHAUST PIPE	Not Necessary	581.00 FL	*- FL
30	2		*EXHAUST MOUNTING SET	Not Necessary	126.00 FL	*- FL
31	1		*EXHAUST HEAT SHIELD	Not Necessary	74.00 FL	*- FL
32	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
33	1		*BOOTLID CHROME GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
34	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
35	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
36	2		*TAIL LAMP PANEL	Not Necessary	160.00 FS	*- FS
37	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
38	1		*REAR BUMPER REVERSE SENSOR SET	Necessary	300.00 FS	*200.00 FS
39	1		*REAR WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
40	2		*REAR FENDER SEALANT	Not Necessary	500.00 FS	*- FS
41	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
42	2		*REAR FENDER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
43	1		*END PANEL SEALANT	Necessary	250.00 FS	*40.00 FS
44	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
45	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

5/31/22, 11:59 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					11,639.00	3,451.00
- List Item Discount on L Items 10.00/10.00% (\$)					907.90	309.10
Total Parts (\$)					10,731.10	3,141.90
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS.	New	2,400.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS.	New	1,400.00	700.00
3	TO RNR REAR WINDSCREEN.	New	300.00	0.00
4	TO RNR REAR EXHAUST.	New	250.00	0.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION.	New	150.00	30.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY.	New	400.00	60.00
7	TO CHECK WATER LEAK.	New	150.00	0.00
8	TO RNR FUEL TANK.	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS.	New	600.00	0.00
10	TO RNR REAR BOOT MECHANISM.	New	350.00	60.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION.	New	150.00	30.00
12	TO PERFORM RUST PROOFING.	New	400.00	40.00
13	TO RNR REAR DOOR MECHANISM.	New	400.00	0.00
Gross Labour Cost (\$\$)			7,200.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >