

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |       |                       |  |
|---|--|--|-----------------|-------|-----------------------|--|
|   | SOMPO INSURAN  | CE SINGAPORE PL                            | F               | Ref:  | CS/SMO21008214/Kqf3n2 |  |
|   | 50 RAFFLES PLAC<br>SINGAPORE LAND  | CE #03-03<br>D TOWERSINGAPORE 048623       | С               | Date: | 10/09/2021            |  |
|   |  |  | C               | Code: | SMO                   |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |  |                 |       |                       |  |
|   | Insured Veh.   | SGS 19P                                    | Veh. Inspected  |       | SMT 7377H             |  |
|   | Policy No.   |  | Coverage (\$)   |       | 0.00                  |  |
|   | Claim No.  | CMTD2102301/RUC                            | Excess (\$)     |       | 0.00                  |  |
|   | Assign From  | GRACE TEO                                  | Assign Date     |       | 04/08/2021            |  |
| 2. Vehicle Particulars & Condition                                |  |  |                 |       |                       |  |
|   | Make & Model   | BMW 420I (A)                               | c.c             |       | 1998                  |  |
|   | Engine No.   | HIDDEN                                     | Year of Reg.    |       | 2019                  |  |
|   | Chassis No.  | WBA4S32060AG24647                          | Colour          |       | METALLIC PEARL WHITE  |  |
|   | Odometer   | 30089 KM                                   | Steering        |       | IN ORDER              |  |
|   | Brakes   | IN ORDER                                   | Modification    |       | STANDARD ALLOY RIM    |  |
|   | General  | GOOD                                       |                 |       |                       |  |
| 3.  | 3. Conditions of Tyres   |  |                 |       |                       |  |
|   |  | Size                                       | Make            |       | Balance               |  |
|   | R/H Front Tyre   | 225/45 R18                                 | PIRELLI         |       | 7 mm                  |  |
|   | L/H Front Tyre   | 225/45 R18                                 | PIRELLI         |       | 7 mm                  |  |
|   | R/H Rear Tyre  | 225/45 R18                                 | PIRELLI         |       | 7 mm                  |  |
|   | L/H Rear Tyre  | 225/45 R18                                 | PIRELLI         |       | 7 mm                  |  |
| 4.  | <u> </u>   |  |                 |       |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  |  |                 |       |                       |  |
|   | DAMAGES SEE DETAILS.   |  |                 |       |                       |  |
| 5.  | General Information  |  |                 |       |                       |  |
|   | Accident Date  | 29/07/2021                                 | Inspection Date |       | 18/08/2021            |  |
|   | Survey held at   | BLK 1 SIN MING INDUSTRIAL SECTOR C #01-135 |                 |       |                       |  |
|   | Repairer   | epairer A T AUTO CONSULTANT                |                 |       |                       |  |
| 5a.   | Remarks  |  |                 |       |                       |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |       |                       |  |
| 5b.   | Estimate Days of Repair  |  |                 |       |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days   |  |                 |       |                       |  |