

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 801U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-------------------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR SMART KEY ANTENNA | TO REPAIR SEE LABOUR | 40.50 | - |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 459.40 | - |
| 1 | REAR BUMPER REINFORCEMENT | TO REPAIR SEE LABOUR | 394.80 | - |
| 2 | REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$138.10 | TO REPAIR SEE LABOUR | 276.20 | - |
| 1 | REAR BUMPER CENTRE MOULDING ASSY | CUT | 451.25 | 451.25 |
| 1 | REAR BUMPER LOWER CENTRE MOULDING ASSY | TO REPAIR SEE LABOUR | 155.00 | - |
| 10 | REAR BUMPER COVER CLIPS @\$2.20 | NECESSARY | 22.00 | 22.00 |
| 1 | REAR BUMPER FOG LAMP | TO REPAIR SEE LABOUR | 201.50 | - |
| 1 | REAR BUMPER TOWING COVER | TO REPAIR SEE LABOUR | 98.80 | - |
| | LESS 20% DISCOUNT | | -419.89 | -94.65 |
| | | | 1,679.56 | 378.60 |
| | NETT ITEMS | | | |
| 1 | REAR BUMPER REVERSE SENSOR (N) | CUT | 180.00 | 180.00 |
| 1 | REAR NO. PLATE W/TRIM COVER (N) | CUT | 55.00 | 55.00 |
| | LESS 10% DISCOUNT | | -23.50 | -23.50 |
| | | | 211.50 | 211.50 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR SMART KEY ANTENNA, REAR BUMPER, REAR BUMPER REINFORCEMENT, REAR BUMPER REINFORCEMENT BRACKET (LH/RH), REAR BUMPER LOWER CENTRE MOULDING ASSY, REAR BUMPER FOG LAMP AND REAR BUMPER TOWING COVER. | | 400.00 | 350.00 |
| | SPRAY PAINTING CHARGE. | | 300.00 | 250.00 |



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------|-----------|------------------------------|-------------------|
| | REMOVE / REFIX REVERSE SENSOR. | | 120.00 | 30.00 |
| | | | 820.00 | 630.00 |
| | GRAND TOTAL | | 2,711.06 | 1,220.10 |

| RECOMMENDED COST OF REPAIRS (CONFIRMED | | | 1,220.10 |
|--|--|--|----------|
|--|--|--|----------|

Report Ref No. NS/INC21008215/Vuce2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser