



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 3269S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	DENTED	499.90	499.90
10	FRT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRT FENDER LH	DENTED	945.30	945.30
1	FRT FENDER (HYBRID) LH	NECESSARY	86.50	86.50
1	FRT FENDER SHIELD LH	TO REPAIR SEE LABOUR	198.50	-
1	WING MIRROR OUTER COVER LH	TO REPAIR SEE LABOUR	141.90	-
1	FRT WHEEL CAP LH	CUT	177.70	177.70
	LESS 25% DISCOUNT		-517.95	-432.85
			1,553.85	1,298.55
LABOUR				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER SHIELD LH AND WING MIRROR OUTER COVER LH.		800.00	525.00
	SPRAY PAINTING CHARGE.		700.00	500.00
	TUFF KOTE.		60.00	30.00
			1,560.00	1,055.00
GRAND TOTAL			3,113.85	2,353.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,900.00

Report Ref No. NS/INC21008216/Vvce2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.