

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21008217/UGA3Q2

Date:

16/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MPC0001342_02

Claimant Vehicle No : SMP6973P**Insured Vehicle No :**

SKM8118T

Date of Loss: 04/08/2021

Nature of Claim:

TP

Claim No:

MPC2021D0003266

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMP6973P**

Make & Model: TOYOTA NOAH HYBRID, 1.8 (A)

Engine No: 2ZR0D68094

Reg. Date: 10/10/2019 (Man. Year: 2019)

Chassis No: ZWR800387668

Colour: Black

Odometer: 99076 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tourador 7 mm	Rear Left Side:	Tourador 7 mm
Front Right Side:	Tourador 7 mm	Rear Right Side:	Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,591.10	5,556.15	9,034.95	61.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,960.00	1,380.00	41.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,931.10	7,516.15	10,414.95	58.08
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	17,931.10	6,000.00	11,931.10	66.54
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,247.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment: 04/08/2021

Date Inspected: 04/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2021)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6973P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Dented/ Bent	845.10 F	*845.10 FL
2	1		*FRONT FENDER INNER SHIELD O/S	Deformed	299.20 F	*172.10 FL
3	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
4	1		*FRONT FENDER HYBRID EMBLEM O/S	Necessary	145.00 F	*125.00 FL
5	1		*FRONT SPORT RIM O/S	Repair	1,200.00 F	*- FL
6	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	485.20 F	*- FL
7	1		*FRONT KNUCKLE ARM O/S	Not Necessary	655.20 F	*- FL
8	1		*FRONT DOOR O/S	Badly Dented	1,645.10 F	*1,545.15 FL
9	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Necessary	182.40 F	*181.10 FL
10	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Shorted	847.90 F	*747.90 FL
11	2		*FRONT DOOR HINGES	Not Necessary	210.00 F	*- FL
12	1		*FRONT DOOR CHECKER O/S	Twisted	151.00 F	*151.00 FL
13	1		*FRONT DOOR INNER LOCK O/S	Shorted	683.20 F	*663.20 FL
14	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Torn	980.20 F	*960.15 FL
15	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 F	*50.00 FL
16	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	115.00 F	*100.00 FL
17	1		*FRONT DOOR SPEAKER O/S	Cracked	288.90 F	*281.50 FL
18	1		*FRONT DOOR INNER RUBBER O/S	Necessary	366.50 F	*292.30 FL
19	1		*FRONT DOOR MIRROR ASSY O/S	Not Necessary	1,105.20 F	*- FL
20	1		*SLIDING DOOR O/S	Repair	1,866.20 F	*- FL
21	1		*SLIDING DOOR RUBBER O/S	Cut	322.20 F	*288.50 FL
22	1		*SET SLIDING DOOR FRAME BLACK STICKER O/S	Not Necessary	180.00 F	*- FL
23	1		*ROCKER PANEL O/S	Repair	945.10 F	*- FL
24	1		*ROCKER PANEL GARNISH O/S	Cut / Torn	922.50 F	*905.20 FL
25	1		*SET ROCKER PANEL GARNISH CLIPS O/S	Necessary	50.00 F	*50.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)

14,591.10

7,408.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 0.00/25.00% (S\$)					0.00	1,852.05
Total Parts (S\$)					14,591.10	5,556.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
3	TO DISMANTLE & REFIX FRONT UNDER CARRIAGE	New	150.00	0.00
4	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX SLIDING DOOR MECHANISM	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	680.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,080.00
Gross Labour Cost (S\$)			3,340.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >