

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21008218/AES3Q2  
**Date:** 10/12/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100466450   |
| <b>Claimant Vehicle No :</b> | SMV3233E                             | <b>Insured Vehicle No :</b> | SLC4686L     |
| Date of Loss:                | 03/08/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 4199161924SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMV3233E</b>                   |             |                   |
| Make & Model:               | AUDI Q3, 2.0 TFSI (A)             | Engine No:  | CZDC04288         |
| Reg. Date:                  | 25/09/2020 (Man. Year: 2020)      | Chassis No: | WAUZZZF30M1005182 |
| Colour:                     | Blue                              | Odometer:   | 10671 km          |
| Engine Capacity:            | 1395 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/65 R17  | Rear Tyre Size:  | 215/65 R17  |
| Front Left Side:  | Falken 6 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 10,373.00         | 7,141.84          | 3,231.16          | 31.15         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 6,202.00          | 3,510.00          | 2,692.00          | 43.41         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>16,575.00</b>  | <b>10,651.84</b>  | <b>5,923.16</b>   | <b>35.74</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | <b>1,160.25</b>   | <b>745.63</b>     | <b>414.62</b>     | <b>35.74</b>  |

|                          |                  |                                                 |                  |              |
|--------------------------|------------------|-------------------------------------------------|------------------|--------------|
| <b>Nett Amount (S\$)</b> | <b>17,735.25</b> | <b>11,397.47</b>                                | <b>6,337.78</b>  | <b>35.74</b> |
|                          |                  | <b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b> | 240.00           |              |
|                          |                  | <b>+ Doc/Search Fee (S\$)</b>                   | 2.00             |              |
|                          |                  | <b>Nett Liability (S\$)</b>                     | <b>11,639.47</b> |              |

INSPECTION

Date of Assignment: 11/08/2021

Date Inspected: 11/08/2021

Estimated Period of Repair: 4.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition               | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------|-------------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                       | Deformed                | 1,008.00 FS | *806.40 FS   |
| 2   | 1   |          | *FRONT BUMPER CLOSING ELEMENT -RH   | Not Necessary           | 59.00 FS    | *- FS        |
| 3   | 1   |          | *FRONT BUMPER LOWER CLOSING ELEMENT | Not Necessary           | 190.00 FS   | *- FS        |
| 4   | 1   |          | *FRONT BUMPER SPOILER               | Cut                     | 383.00 FS   | *306.40 FS   |
| 5   | 1   |          | *FRONT BUMPER AIR GRILLE -RH        | Not Necessary           | 153.00 FS   | *- FS        |
| 6   | 1   |          | *FRONT BUMPER GUIDE SECTION -RH     | Cracked                 | 39.00 FS    | *30.48 FS    |
| 7   | 1   |          | *FRONT BUMPER TOP COVER             | Not Necessary           | 123.00 FS   | *- FS        |
| 8   | 1   |          | *CAUTION STICKER                    | Not Necessary           | 14.00 FS    | *- FS        |
| 9   | 1   |          | *AIR-CONDITIONER STICKER            | Not Necessary           | 8.00 FS     | *- FS        |
| 10  | 1   |          | *FRONT FENDER -RH                   | Dented                  | 1,286.00 FS | *1,028.80 FS |
| 11  | 1   |          | *FRONT FENDER ATTACHMENT PART-RH    | Not Necessary           | 63.00 FS    | *- FS        |
| 12  | 1   |          | *FRONT FENDER BRACE-RH              | Bent                    | 88.00 FS    | *69.76 FS    |
| 13  | 1   |          | *FRONT FENDER BRACKET -RH           | Not Necessary           | 32.00 FS    | *- FS        |
| 14  | 1   |          | *FRONT PARKING AID SENSOR(NPA)      | Not Necessary           | 0.00 FS     | *- FS        |
| 15  | 4   |          | *FRONT PARKING AID SENSOR SEAL      | Not Necessary           | 14.00 FS    | *- FS        |
| 16  | 1   |          | *HEADLIGHT MOUNTING-RH              | Not Necessary           | 118.00 FS   | *- FS        |
| 17  | 1   |          | *HEADLIGHT -RH                      | Cut                     | 5,589.00 FS | *4,471.20 FS |
| 18  | 1   |          | *HEADLIGHT WASHER CYLINDER -RH      | Not Necessary           | 210.00 FS   | *- FS        |
| 19  | 2   |          | *FRONT WHEEL ARCH COVER LH-RH       | N/S Necessary / O/S Cut | 536.00 FS   | *428.80 FS   |
| 20  | 1   |          | *SUNDRIES                           | Not Necessary           | 350.00 FS   | *- FS        |
| 21  | 1   |          | *FRONT BUMPER LOWER GRILLE-RH       | Not Necessary           | 110.00 FS   | *- FS        |

F=Franchise part. S=SpcNett.

|                          |                  |                 |
|--------------------------|------------------|-----------------|
| <b>Total Parts (S\$)</b> | <b>10,373.00</b> | <b>7,141.84</b> |
|--------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                                    | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                                                                                                |          |                 |                 |
| 1                              | TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New      | 480.00          | 480.00          |
| 2                              | TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE                                                                            | New      | 400.00          | 250.00          |
| 3                              | TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT RE-ORGANIZE CRASH MANAGEMEN COMPONENTS REINSTALL ALL PARTS REMOVED     | New      | 2,400.00        | 1,000.00        |
| 4                              | TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER                                                                                                   | New      | 2,200.00        | 1,100.00        |
| 5                              | TO RESPRAY PAINT COATING ON AFFECTED AREA (BY OWNER)                                                                                           | New      | 280.00          | 280.00          |
| 6                              | TO REAPPLY HEADLIGHT PROTECTION FILM (BY OWNER)                                                                                                | New      | 250.00          | 208.00          |
| 7                              | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                  | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                                |          | <b>6,202.00</b> | <b>3,510.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >