



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3644Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,345.00	1,345.00
8	REAR BUMPER CLIPS	NECESSARY	24.00	24.00
1	REAR BUMPER REINFORCEMENT BEAM	NOT NECESSARY	625.00	-
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	148.00	-
1	REAR BUMPER CENTRE SUPPORT BRACKET GARNISH	NOT NECESSARY	195.00	-
1	REAR BUMPER CENTRE MOULDING	NECESSARY	190.00	190.00
	LESS 10% DISCOUNT		-	-155.90
			2,527.00	1,403.10
	<u>SPECIAL NETT ITEMS</u>			
1	SET 4PC REAR REVERSE SENSOR WITH MONITOR SCREEN (SN)	DAMAGED	480.00	300.00
			480.00	300.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	SPRAY PAINTING.		300.00	250.00
	TO REMOVE & REFIX REAR INTERIOR UPSHOLY.	NOT NECESSARY	80.00	-
	TO MEASURE, DRILL THE REPLACED REAR BUMPER, POSITION & REINSTALL REAR REVERSE SENSOR, CONTROL UNIT & TEST FOR FUNCTIONING.		80.00	50.00
	REMOVING ALL DAMAGE PARTS AND REPLACING OF THE NEW PARTS ETC.		250.00	200.00
			760.00	530.00
	GRAND TOTAL		3,767.00	2,233.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/AGI21008228/Atf3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.