

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD INV No. AC2105855

36 ROBINSON ROAD INV Date 18/08/2021

#16-01 CITY HOUSE Reference CC4/FCI21008229/Kra3q2

SINGAPORE 068877 Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMV 9277P

Insured Veh. SKF 2466P

Claim No. D21002223MFZH/2

Policy No. D-21097526MFZH

Accident Date 30/07/2021

Inspection Date 04/08/2021

Description	Total
Survey Inspection	216.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	216.00
GST (7%)	15.12
Grand Total	231.12

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CC4/FCI21008229/Kra3q2		
	36 ROBINSON RC #16-01 CITY HOUS	AD SESINGAPORE 068877	Date	18/08/2021		
			Code	e: FCI2		
1.		Policy Particulars	:- THIRD PARTY CLA	IM		
	Insured Veh.	SKF 2466P	Veh. Inspected	SMV 9277P		
	Policy No.	D-21097526MFZH	Coverage (\$)	0.00		
	Claim No.	D21002223MFZH/2	Excess (\$)	0.00		
	Assign From	KAREN TAN	Assign Date	03/08/2021		
2.		Vehicle Partic	culars & Condition			
	Make & Model	TOYOTA PRIUS (A)	c.c	1798		
	Engine No.	HIDDEN	Year of Reg.	2020		
	Chassis No.	JTDKB3FU603091322	Colour	METALLIC SILVER		
	Odometer	65416 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Conditi	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	195/65 R15	DUNLOP	9 mm		
	L/H Front Tyre	195/65 R15	DUNLOP	9 mm		
	R/H Rear Tyre	195/65 R15	DUNLOP	7 mm		
	L/H Rear Tyre	195/65 R15	DUNLOP	7 mm		
4.		Description	on of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.		Genera	Information			
	Accident Date	30/07/2021	Inspection Date	04/08/2021		
	Survey held at	CITY AUTO PTE LTD	•			
		BLK 8, SIN MING IND. ESTATE				
		#01-60/62 Sector C				
		SINGAPORE 575643.				
5a.	I		emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		·	Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days					
			1			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 9277P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER LOWER LID	DENTED / CUT	374.50	374.50
	LESS 25% DISCOUNT		-93.63	-93.62
			280.87	280.88
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
			250.00	-
	<u>LABOUR</u>			
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS.		300.00	80.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		300.00	200.00
			600.00	280.00
	GRAND TOTAL		1,130.87	560.88

RECOMMENDED COST OF REPAIRS			560.88
-----------------------------	--	--	--------

Report Ref No. CC4/FCI21008229/Kra3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 9277P

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMV 9277P

RE-INSPECTION





