

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI21008230/Gvf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 12/08/2021	
			Cod	e: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMD 7390C	Veh. Inspected	GN 6288R	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10010773/CD	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	04/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE 2.8	c.c	2754	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	GDH2012002928	Colour	WHITE	
	Odometer	105940 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195 R16	KAPSEN	6 mm	
	L/H Front Tyre	195 R16	KAPSEN	6 mm	
	R/H Rear Tyre	195 R16	KAPSEN	6 mm	
	L/H Rear Tyre	195 R16	KAPSEN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	03/07/2021	Inspection Date	06/08/2021	
	Survey held at	AB ENGINEERING PTE LTD			
		25 SENANG CRESCENT, SINGAPORE 416598			
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Estimate Days of Repair

3 Working Days