

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR21008231/Vuf3e2	
	60 WOODLANDS I E4SINGAPORE 75		Date:	17/08/2021		
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHD 6171J	Veh. Inspected		FBR 7500J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/07/21/2059	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		04/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	YAMAHA XSR155	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3RG4760LK009154	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/90 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	100/90 R17	BRIDGESTONE		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	27/07/2021	Inspect Date /	Time	06/08/2021 (02:45 PM)	
	Survey held at	BEAR'S GARAGE LLP	-			
	25 KAKI BUKIT ROAD 4 #03-62 SYNERGY@KB SINGAPORE 417800					
5a.	Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLI	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					

Report Ref No. CS3/SMR21008231/Vuf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser