

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2107183

3 ANSON ROAD #16-00 INV Date 18/10/2021

SPRINGLEAF TOWER
SINGAPORE 079909
Reference CC6/CTI21008233/Kba3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKV 3518H

Insured Veh. SKV 7234A

Claim No. SNM21D204388

Policy No. DMPCSNW00099162002

Accident Date 26/07/2021

Inspection Date 03/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile								
	CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CC6/CTI21008233/Kba3q2				
	3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date:	18/10/2021				
			Code:	СТІ				
1.		Policy Particulars :	- THIRD PARTY CLAII	И				
	Insured Veh.	SKV 7234A	Veh. Inspected	SKV 3518H				
	Policy No.	DMPCSNW00099162002	Coverage (\$)	0.00				
	Claim No.	SNM21D204388	Excess (\$)	0.00				
	Assign From		Assign Date	03/08/2021				
2.		Vehicle Partic	ulars & Condition					
	Make & Model	MERCEDES BENZ C180 (A)	c.c	1595				
	Engine No.	HIDDEN	Year of Reg.	2015				
	Chassis No.	WDD2050402R088431	Colour	METALLIC SILVER				
	Odometer	68000 KM	Steering	IN ORDER				
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM				
	General	GOOD						
3.		Condition	ons of Tyres					
		Size	Make	Balance				
	R/H Front Tyre	225/50 R17	CONTINENTAL	7 mm				
	L/H Front Tyre	225/50 R17	CONTINENTAL	7 mm				
	R/H Rear Tyre	225/50 R17	CONTINENTAL	7 mm				
	L/H Rear Tyre	225/50 R17	CONTINENTAL	7 mm				
4.	4. Description of Damages							
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.							
	DAMAGES SEE DETAILS.							
5.		General	Information					
	Accident Date	26/07/2021	Inspection Date	03/08/2021				
	Survey held at	LOH HENG						
		BLK 176 #03-08 SIN MING DRIVE SINGAPORE 575721						
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

Estimate By Our Adjusted

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 3518H

(TO ITS PRE-ACCIDENT CONDITION)

Qty	Description of Parts	Condition	Workshop (\$))	(\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	BUCKLED	2,280.00	1,660.00
1	REAR BUMPER CHROME	DENTED	280.00	229.60
2	BUMPER SENSORS @\$216.00	SHORTED	452.00	452.00
1	BUMPER SPONE	SERVICEABLE	198.00	-
1	TOW COVER	DENTED	85.00	65.00
	LESS 10% DISCOUNT		-329.50	-240.66
			2,965.50	2,165.94
	<u>LABOUR</u>			
	LABOUR TO CHARE FRONT DAMAGED PARTS ,REMOVE AND REFIX NEW PARTS.		380.00	220.00
	TO RESPRAY +PUTTY ON THE REPLACEMENT PARTS.		500.00	250.00
			880.00	470.00
	GRAND TOTAL		3,845.50	2,635.94
	RECOMMENDED COST OF LUMP SUM REPAIRS			2,100.00

Report Ref No. CC6/CTI21008233/Kba3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 3518H

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 3518H

RE-INSPECTION



