

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008234/T1TCQ2**Date:** 01/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00002832100

Claimant Vehicle No : GZ2882M **Insured Vehicle No :** SLA7763M

Date of Loss: 31/07/2021 Nature of Claim: TP Claim No: SNM21D204280/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ2882M**

Make & Model: TOYOTA HIACE, 2.5 (M) Engine No: 2KD1423718

Reg. Date: 22/02/2006 (Man. Year: 2006) Chassis No: JTFHS02P600040095

Colour: Pink Odometer: 389598 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,085.00	4,621.06	16,463.94	78.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	1,650.00	5,850.00	78.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,585.00	6,271.06	22,313.94	78.06
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	28,585.00	4,800.00	23,785.00	83.21
+ GST 7.00/7.00% (\$\$)	2,000.95	336.00	1,664.95	83.21
Nett Amount (\$\$)	30,585.95	5,136.00	25,449.95	83.21

INSPECTION

Date of Assignment: 04/08/2021

Date Inspected: 05/08/2021 Inspected At: AP Automotive Services Pte Ltd
56 Loyang Way, #04-04 Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Apr 2022)	
Parts:	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ2882M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,969.00 FL	*1,855.00 FL
2	1		*TAILGATE HANDLE GARNISH	Not Necessary	155.00 FL	*- FL
3	1		*TAILGATE LOGO -TOYOTA	Necessary	75.00 FL	*75.00 FL
4	1		*TAILGATE LOCK	Bent	275.00 FL	*235.10 FL
5	1		*TAILGATE LOCK COVER	Not Necessary	52.00 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Necessary	62.00 FL	*- FL
7	1		*TAILGATE INNER BOARD	Cracked	408.00 FL	*325.00 FL
8	2		*TAILGATE HINGE L+R	Not Necessary	152.00 FL	*- FL
9	2		*TAILGATE DAMPER L+R	Not Necessary	710.00 FL	*- FL
10	2		*TAILGATE STOPPER L+R	Not Necessary	50.00 FL	*- FL
11	1		*TAILGATE WEATHERSTRIP	Cut	395.00 FL	*288.60 FL
12	2		*TAIL LAMP L+R	Cracked	600.00 FL	*513.80 FL
13	2		*TAIL LAMP PANEL L+R (NPA)	Not Necessary	0.00 FL	*- FL
14	2		*REAR BUMPER RETAINER L+R	Not Necessary	58.00 FL	*- FL
15	1		*REAR SIDE BUMPER L+R	O/S Not Necessary/N/S Deformed	200.00 FL	*100.00 FL
16	1		*REAR SIDE BUMPER RETAINER L+R	O/S Not Necessary/N/S Deformed	60.00 FL	*30.00 FL
17	2		*REAR FENDER L+R(NPA)	Not Necessary	0.00 FL	*- FL
18	2		*REAR FENDER COWLING L+R (NPA)	Not Necessary	0.00 FL	*- FL
19	1		*END PANEL	Bent	387.00 FL	*358.20 FL
20	1		*END PANEL INNER PANEL	Repair	1,155.00 FL	*- FL
21	1		*END PANEL TOP GARNISH	Bent	269.00 FL	*180.71 FL
22	1		*REAR QUARTER PANEL RH	Not Necessary	374.00 FL	*- FL
23	1		*FLOOR PANEL	Not Necessary	2,879.00 FL	*- FL
24	1		*EXHAUST PIPE	Not Necessary	591.00 FL	*- FL
25	2		*SET EXHAUST MOUNTING	Not Necessary	118.00 FL	*- FL
26	1		*EXHAUST HEAT SHIELD	Not Necessary	91.00 FL	*- FL
27	1		*SPARE TYRE BRACKET	Not Necessary	295.00 FL	*- FL
28	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
29	1		*TAILGATE HANDLE GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
30	1		*TAILGATE OUTER CHROME	Not Necessary	1,500.00 FS	*- FS
31	1		*TAILGATE STICKER -70KM/H	Necessary	80.00 FS	*30.00 FS
32	1		*TAILGATE STICKER -QR CODE	Necessary	250.00 FS	*30.00 FS
33	1		*TAILGATE STICKER -EMERGENCY EXIT	Necessary	80.00 FS	*10.00 FS
34	1		*TAILGATE STICKER-HOTLINE }	Necessary	400.00 FS	*200.00 FS
35	1		*TAILGATE STICKER-NUMBER }	Necessary	400.00 FS	*- FS
36	1		*TAILGATE INNER BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
37	1		*REAR NUMBER PLATE	Not Necessary	200.00 FS	*- FS
38	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
39	2		*TAIL LAMP OUTER CHROME	Necessary	600.00 FS	*300.00 FS
40	1		*REAR BUMPER	Deformed	3,000.00 FS	*700.00 FS
41	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
42	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
43	1		*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
44	1		*REAR FENDER COWLING	Not Necessary	100.00 FS	*- FS
45	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*END PANEL INNER PANEL SEALANT	Not Necessary	200.00 FS	*- FS
47	2		*REAR QUARTER PANEL SEALANT	Not Necessary	240.00 FS	*- FS
48	1		*FLOOR PANEL SEALANT	Not Necessary	300.00 FS	*- FS
49	1		*FLOOR PANEL TOP BOARD	Not Necessary	4,000.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,930.00	5,611.41
- List Item Discount on L Items 25.00/25.00% (\$)	2,845.00	990.35
Total Parts (\$)	21,085.00	4,621.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	2,000.00	700.00
3	TO RNR REAR WINDSCREEN	New	400.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR TRIMS AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	20.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
9	TO RNR REAR TAILGATE MECHANISM	New	400.00	60.00
10	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
11	TO PERFORM RUST PROOFING	New	600.00	30.00
Gross Labour Cost (\$\$)			7,500.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >