

ASS. REC. BY:

Tang JH

REF:

CS/CT/21008234/Titc

ASSIGNMENT

CoE 2026 Feb

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$30K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GZ 2882M.

Yr Regn:

2006, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace 2.5

C.C.

2494

Colour

Pink

A/C:

Insured / Std / NI / NA

Sp. Reading

38958

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFH302P600040095.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: ☒ NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/15

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habitat.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/8/21 05pm

Survey held at

AP Auto.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

Lump Sum / L.B.A. (?)

Estimation

Date _____
 Vehicle **GZ 2882 M**
 Make/Model **TOYOTA HIACE**
 Chassis No. **JTFHS02P600040095**

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	TAILGATE 1855	1	\$ 1,969.00	\$ 66 1,969.00
2	TAILGATE HANDLE GARNISH	1	\$ 155.00	\$ X nn. 155.00
3	TAILGATE LOGO - TOYOTA	1	\$ 75.00	\$ na 75.00
4	TAILGATE LOCK 235.10	1	\$ 275.00	\$ 66 275.00
5	TAILGATE LOCK COVER	1	\$ 52.00	\$ X nn 52.00
6	TAILGATE LOCK CATCH	1	\$ 62.00	\$ X nn 62.00
7	TAILGATE INNER BOARD 325	1	\$ 408.00	\$ out 408.00
8	TAILGATE HINGE L+R	2	\$ 76.00	\$ X nn 152.00
9	TAILGATE DAMPER L+R	2	\$ 355.00	\$ X nn 710.00
10	TAILGATE STOPPER L+R	2	\$ 25.00	\$ X nn. 50.00
11	TAILGATE WEATHERSTRIP 288.60	1	\$ 395.00	\$ out 395.00
12	TAIL LAMP L+R @ 256.90 each 513.80	2	\$ 300.00	\$ out 600.00
13	TAIL LAMP PANEL L+R	2		\$ X nn -
14	REAR BUMPER RETAINER L+R	2	\$ 29.00	\$ X nn 58.00
15	REAR SIDE BUMPER L+R RH X nn	2	\$ (100.00)	\$ LH di 200.00
16	REAR SIDE BUMPER RETAINER L+R RH X nn	2	\$ (30.00)	\$ LH di 60.00
17	REAR FENDER L+R	1		\$ X nn -
18	REAR FENDER COWLING L+R	1		\$ X nn. -
19	END PANEL 358.20	1	\$ 387.00	\$ 66 387.00
20	END PANEL INNER PANEL	1	\$ 1,155.00	\$ 66 1,155.00
21	END PANEL TOP GARNISH 180.71	1	\$ 269.00	\$ 66 269.00
22	REAR QUARTER PANEL RH	1	\$ 374.00	\$ X nn 374.00
23	FLOOR PANEL	1	\$ 2,879.00	\$ X nn 2,879.00
24	EXHAUST PIPE	1	\$ 591.00	\$ X 591.00
25	EXHAUST MOUNTING SET	2	\$ 59.00	\$ X } nn 118.00
26	EXHAUST HEAT SHIELD	1	\$ 91.00	\$ X 91.00
27	SPARE TYRE BRACKET	1	\$ 295.00	\$ X 295.00
	3961.41		Total	\$ 11,380.00
	2971.05		Less 25%	\$ 2,845.00
			Total	\$ 8,535.00

	S/Nett Items			
1	TAILGATE WINDSCREEN SEALANT	1	150	\$ 60 nec 150.00
2	TAILGATE HANDLE GARNISH CLIPS	1	100	\$ X nn 100.00
3	TAILGATE OUTER CHROME	1	1500	\$ X nn 1,500.00
4	TAILGATE STICKER - 70KM/H	1	80	\$ 80.00

5	TAILGATE STICKER - QR CODE	1	250	\$ 30 nec	250.00
6	TAILGATE STICKER - EMERGENCY EXIT	1	80	\$ 10 nec	80.00
7	TAILGATE STICKER - HOTLINE	1	400	\$ 7 200 nec	400.00
8	TAILGATE STICKER - NUMBER	1	400	\$ 7 200 nec	400.00
9	TAILGATE INNER BOARD CLIPS	1	100	\$ 30 nec	100.00
10	REAR NUMBER PLATE	1	200	\$ X nm.	200.00
11	TAIL LAMP CLIPS	1	50	\$ 20 nec	50.00
12	TAIL LAMP OUTER CHROME	2	150 300	\$ 10 300	600.00
13	REAR BUMPER	1	700 3000	\$ 00 3000	3,000.00
14	REAR BUMPER CLIPS	1	100	\$ 30 nec	100.00
15	REAR BUMPER REVERSE SENSOR SET	1	300	\$ 200 nm	300.00
16	REAR FENDER SEALANT	1	200	\$ X 7 nm	200.00
17	REAR FENDER COWLING	1	100	\$ X 7 nm	100.00
18	END PANEL SEALANT	1	200	\$ 40 nec	200.00
19	END PANEL INNER PANEL SEALANT	1	200	\$ X 7 nm	200.00
20	REAR QUARTER PANEL SEALANT	2	120	\$ X 7 nm	240.00
21	FLOOR PANEL SEALANT	1	300	\$ X 7 nm	300.00
22	FLOOR PANEL TOP BOARD	1	4000	\$ X 7 nm	4,000.00
			Total	\$	12,550.00

1470

LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	2400	\$ 600 2,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	2000	\$ 700 2,000.00
3	TO RNR REAR WINDSCREEN	1	400	\$ 120 400.00
3	TO RNR REAR EXHAUST	1	250	\$ 60 X nm 250.00
4	TO CHECK WIRING AND TAILLAMP FUNCTION	1	150	\$ 30 150.00
5	TO RNR REAR TRIMS AND UPHOISTERY	1	400	\$ 60 400.00
6	TO CHECK WATER LEAK	1	150	\$ 20 150.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X nm 600.00
8	TO RNR REAR TAILGATE MECHANISM	1	400	\$ 60 400.00
9	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	1	150	\$ 30 150.00
10	TO PERFORM RUST PROOFING	1	600	\$ 30 600.00
			Total	\$ 7,500.00

1650

Parts Replacement Amount	\$	21,085.00
Total Amount For Labour	\$	7,500.00
Total Amount	\$	28,585.00

Tanfukhi 97495749
 'WP' 5/8/21 @ 5pm
 1/3 resurvey after repair
 tanfukhi@lkhant.com
 0.6 days

2971.05
 1470
 1650
 6091.05
 1/s\$4800
 6 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer
 Signature: _____
 Date: _____