

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008240/T1EA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJL3657D	Insured Vehicle No :	SLN9216U
Date of Loss:	02/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003325

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL3657D	Engine No:	4G18JT1939
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U010591
Reg. Date:	25/11/2008 (Man. Year: 2008)	Odometer:	213033 km
Colour:	Blue		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,688.97	3,657.70	17,031.27	82.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,250.00	1,260.00	3,990.00	76.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,938.97	4,917.70	21,021.27	81.04
Approved Total (Overridden) (S\$)		3,900.00		
(S\$)	25,938.97	3,900.00	22,038.97	84.96
+ GST 7.00/7.00% (S\$)	1,815.73	273.00	1,542.73	84.96
Nett Amount (S\$)	27,754.70	4,173.00	23,581.70	84.96
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,036.45		
Global Sum Settlement (S\$)		5,030.00		

INSPECTION

Date of Assignment:	04/08/2021		
Date Inspected:	05/08/2021	Inspected At:	AP Automotive Services Pte Ltd (HQ) Blk 9006 Tampines Street 93, #01-202 Singapore 528840
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3657D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT WIPER PANEL GARNISH	Not Necessary	416.00 FL	*- FL
2	2	*BONNET HINGE	Not Necessary	144.00 FL	*- FL
3	1	*HEADLAMP L+R	O/S Cracked / N/SNot Necessary	1,382.00 FL	*523.00 FL
4	2	*HEADLAMP BRACKET L+R	Not Necessary	155.60 FL	*- FL
5	2	*FRONT BUMPER RETAINER L+R	Not Necessary	232.00 FL	*- FL
6	1	*FRONT BUMPER REINFORCEMENT BAR	Bent	252.60 FL	*134.00 FL
7	1	*FRONT BUMPER SPONGE	Not Necessary	319.00 FL	*- FL
8	1	*FRONT BUMPER UNDERCOVER	Not Necessary	471.00 FL	*- FL
9	2	*FRONT FENDER L+R	Not Necessary	1,218.00 FL	*- FL
10	2	*FRONT FENDER COWLING L+R	Torn	403.80 FL	*214.00 FL
11	1	*FRONT SUPPORT PANEL	Bent	1,289.00 FL	*558.00 FL
12	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	274.00 FL	*- FL
13	1	*AIRCON CONDENSOR	Not Necessary	786.30 FL	*- FL
14	2	*AIRCON CONDENSOR AIR GUIDE L+R	Not Necessary	288.00 FL	*- FL
15	1	*RADIATOR	Not Necessary	979.00 FL	*- FL
16	1	*RADIATOR FAN COWLING	Not Necessary	456.00 FL	*- FL
17	1	*RADIATOR FAN BLADE	Not Necessary	376.00 FL	*- FL
18	1	*RADIATOR FAN MOTOR	Not Necessary	411.00 FL	*- FL
19	1	*WIPER WASHER TANK	Not Necessary	316.00 FL	*- FL
20	1	*FRONT HORN	Bent	74.00 FL	*74.00 FL
21	1	*BONNET CARBON FIBRE	Cracked	4,000.00 FS	*1,200.00 FS
22	1	*BONNET INSULATOR	Not Necessary	200.00 FS	*- FS
23	1	*FRONT GRILLE	Cracked	900.00 FS	*200.00 FS
24	1	*FRONT BUMPER TOP	Deformed	2,000.00 FS	*800.00 FS
25	1	*FRONT BUMPER LOGO -MITSUBISHI	Not Necessary	200.00 FS	*- FS
26	1	*FRONT BUMPER LOWER	Repair	2,500.00 FS	*- FS
27	2	*FRONT BUMPER FOG LAMP L+R	Not Necessary	800.00 FS	*- FS
28	1	*FRONT BUMPER TAG	Not Necessary	250.00 FS	*- FS
29	1	*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
30	1	*FRONT NUMBER PLATE	Bent	120.00 FS	*45.00 FS
31	2	*FRONT FENDER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
32	1	*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
33	1	*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,713.30	3,808.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,024.33	150.30
Total Parts (\$\$)	20,688.97	3,657.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	500.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	New	150.00	0.00
5	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
6	TO CHECK WATER LEAK	New	150.00	0.00
7	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	0.00
8	TO RNR FRONT RADIATOR	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO PERFORM RUST PROOFING	New	200.00	30.00
11	TO RNR HORN AND TEST FUNCTION	New	150.00	0.00
Gross Labour Cost (\$\$)			5,250.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >