



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7105K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER SIDE BRACKET LH	NOT NECESSARY	55.80	-
1	REAR BUMPER CENTRE MOULDING	TO REPAIR SEE LABOUR	451.25	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	41.45	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
10	REAR BUMPER CLIPS	NOT NECESSARY	22.00	-
1	REAR REINFORCEMENT STAY HH	NOT NECESSARY	138.10	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
	LESS 20% DISCOUNT		-332.32	-
			1,329.28	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
1	REAR NUMBER PLATE W/HOLDER (SN)	NOT NECESSARY	55.00	-
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			285.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER CENTRE MOULDING.		450.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			870.00	630.00
	GRAND TOTAL		2,484.28	630.00

RECOMMENDED COST OF REPAIRS (CONFIRMED)			630.00
--	--	--	---------------

Report Ref No. NS/INC21008243/T1uce2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.