



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 7239Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,100.00	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	48.00	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	220.00	-
1	HEADLAMP LH (CONSISTENT)	CRACKED	3,325.00	3,068.00
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	110.00	-
1	FRONT REINFORCEMENT (CONSISTENT)	NOT NECESSARY	361.65	-
1	FRONT REINFORCEMENT COVER (CONSISTENT)	NOT NECESSARY	52.15	-
1	FRONT HEADLIGHT WASHER ASSEMBLY (CONSISTENT)	NOT NECESSARY	155.95	-
	LESS 5% DISCOUNT		-268.64	-153.40
			5,104.11	2,914.60
	<b><u>LABOUR</u></b>			
	PANEL BEATING AND RENEW OF DAMAGE PARTS ON AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		560.00	250.00
	SPRAY PAINTING ON AFFECTED AREA.		560.00	250.00
	LABOR TO CALIBRATE OF HEADLIGHT TO LTA STANDARD.		120.00	40.00
			1,240.00	540.00
	<b>GRAND TOTAL</b>		<b>6,344.11</b>	<b>3,454.60</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,750.00</b>

Report Ref No. CC4/ASM21008245/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.