

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008246/KYA3Q2**Date:** 30/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800042055
Claimant Vehicle No :	SCN928P	Insured Vehicle No :	SKC8000B
Date of Loss:	31/07/2021	Nature of Claim:	TP
		Claim No:	4066311779SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCN928P	Engine No:	CYG002496
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G0FN051550
Reg. Date:	16/06/2015 (Man. Year: 2015)	Odometer:	86865 km
Colour:	Metallic Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R18	Rear Tyre Size:	245/45Z R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,801.90	8,214.79	14,587.11	63.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,080.00	1,090.00	50.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,971.90	9,294.79	15,677.11	62.78
Approved Total (Overridden) (S\$)		7,400.00		
Nett Amount (S\$)	24,971.90	7,400.00	17,571.90	70.37
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	04/08/2021	
Date Inspected:	04/08/2021	Inspected At: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cracked	2,399.79 FL	*2,399.79 FL
2	1	*RH FRONT BUMPER SIDE BRACKET	Cracked	68.99 FL	*68.99 FL
3	1	*RH FRONT BUMPER SIDE RETAINER	Cracked	61.90 FL	*61.90 FL
4	10	*FRONT BUMPER RIVETS	Necessary	100.00 FL	*100.00 FL
5	1	*FRONT BUMPER LOWER CENTRE GRILLE	Serviceable	200.00 FL	*- FL
6	1	*FRONT BUMPER LOWER CENTRE GRILLE CHROME MOULDING	Serviceable	388.60 FL	*- FL
7	1	*RH FRONT BUMPER LOWER SIDE GRILLE	Missing	488.91 FL	*488.91 FL
8	1	*FRONT BUMPER TOWING COVER	Serviceable	130.91 FL	*- FL
9	1	*FRONT BUMPER CENTRE BRACKET	Repair	133.71 FL	*- FL
10	1	*RH FRONT BUMPER PARKING SENSOR -OUTER	Missing	249.79 FL	*249.79 FL
11	1	*RH FRONT BUMPER PARKING SENSOR -CENTRE	Serviceable	249.79 FL	*- FL
12	2	*FRONT BUMPER PARKING SENSOR BRACKET -OUTER	Repair	267.42 FL	*- FL
13	2	*FRONT BUMPER PARKING SENSOR BRACKET -CENTRE	Serviceable	267.42 FL	*- FL
14	1	*FRONT BUMPER UNDER COVER	*Check	366.56 FL	*- FL
15	1	*FRONT BUMPER REINFORCEMENT	Repair	1,009.79 FL	*- FL
16	1	*RH FRONT BUMPER REINFORCEMENT BRACKET	Repair	460.71 FL	*- FL
17	1	*FRONT BUMPER SPONGE	Serviceable	366.86 FL	*- FL
18	1	*FRONT SUPPORT PANEL	*Check	1,399.60 FL	*- FL
19	1	*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	133.67 FL	*- FL
20	10	*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	117.10 FL	*- FL
21	1	*RH HEADLAMP PANEL	Repair	161.70 FL	*- FL
22	1	*RH HEADLAMP SIDE BRACKET	*Check	169.97 FL	*- FL
23	1	*FRONT GRILLE	Cracked	1,777.71 FL	*1,777.71 FL
24	1	*RH FRONT FENDER	Bent	955.00 FL	*955.00 FL
25	1	*RH FRONT FENDER STONE PROTECTION STICKER	Necessary	139.75 FL	*139.75 FL
26	1	*RH FRONT FENDER INNER BRACKET	*Check	167.71 FL	*- FL
27	1	*RH FRONT FENDER INNER SHIELD	Torn	185.50 FL	*185.50 FL
28	1	*RH FRONT FENDER INNER SHIELD UNDER COVER	Cracked	367.11 FL	*367.11 FL
29	1	*RH HEADLAMP	Serviceable	8,840.00 FL	*- FL
30	1	*RH HEADLAMP NOZZLE PUMP	*Check	366.99 FL	*- FL
31	1	*RH HEADLAMP NOZZLE PUMP COVER	Serviceable	133.71 FL	*- FL
32	1	*RH HEADLAMP NOZZLE PUMP HOSE	Serviceable	175.10 FL	*- FL
33	1	*RH FRONT RIM	Dented	2,333.10 FL	*2,333.10 FL
34	1	*RH HORN	Serviceable	233.91 FL	*- FL
35	1	*FRONT NUMBER PLATE	Serviceable	40.00 FS	*- FS
36	1	*RH FRONT TYRE	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,288.78	9,127.55
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,486.88	912.76
Total Parts (\$\$)	22,801.90	8,214.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	800.00	500.00
2	TO FOCUS HEADLAMPS .TO CHECK FRONT WIRING AND LIGHTING OPERATION	New	50.00	20.00
3	TO REMOVE AIRCON CONDENSER ,PIPES AND DRIERS VACUUM AND RECHARGE GAS	New	100.00	0.00
4	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	120.00	60.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,100.00	500.00
Gross Labour Cost (\$\$)			2,170.00	1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >