

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008248/R1QCN2**Date:** 06/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00161432001

Claimant Vehicle No : SLJ686B **Insured Vehicle No :** SMQ8898E

Date of Loss: 02/08/2021 Nature of Claim: TP Claim No: SNM21D204313/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ686B**

Make & Model: HONDA VEZEL, 1.5 HYBRID (A) Engine No: LEB5910228

Reg. Date: 28/11/2016 (Man. Year: 2016) Chassis No: RU31210216

Colour: Brown Odometer: 278889 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 ZR18 Rear Tyre Size: 225/45 ZR18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,269.50	1,715.20	2,554.30	59.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	1,160.00	1,320.00	53.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,749.50	2,875.20	3,874.30	57.40
Approved Total (Overridden) (\$\$)		2,300.00		
Nett Amount (\$\$)	6,749.50	2,300.00	4,449.50	65.92

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 18/08/2021 Inspected At: 1017 YISHUN INDUSTRIAL PARK A,
#01-240, YISHUN INDUSTRIAL PARK A,
SINGAPORE 768759
REPAIRER: KENT SENG CAR SERVICES

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ686B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT SIDE ROCKER PANEL MOULDING	Repair	377.50 F	*- FL
2	1		*RIGHT SIDE FRONT DOOR	Bent	1,280.00 F	*980.00 FL
3	1		*RIGHT SIDE FRONT DOOR STICKER (HORIZONTAL)	Necessary	48.00 F	*48.00 FL
4	1		*RIGHT SIDE FRONT DOOR STICKER (VERTICAL)	Not Necessary	38.00 F	*- FL
5	1		*RIGHT SIDE REAR DOOR	Bent	1,030.00 F	*1,030.00 FL
6	1		*RIGHT SIDE REAR DOOR STICKER (HORIZONTAL)	Necessary	48.00 F	*48.00 FL
7	1		*RIGHT SIDE REAR DOOR STICKER (VERTICAL)	Necessary	38.00 F	*38.00 FL
8	1		*REAR RIGHT SIDE FENDER	Not Necessary	980.00 F	*- FL
9	1		*REAR WHEEL ARCH GARNISH (RIGHT)	Repair	195.00 F	*- FL
10	8		*REAR WHEEL ARCH GARNISH CLIPS (RIGHT)	Not Necessary	40.00 F	*- FL
11	1		*REAR WIND SCREEN MOULDING	Not Necessary	195.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,269.50	2,144.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	428.80
Total Parts (\$\$)	4,269.50	1,715.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTENING,REPAIRING AND REALIGNING ON AFFECTED PORTION,DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS	New	1,100.00	500.00
2	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED PANELS,RIGHT SIDE FRONT DOOR,RIGHT SIDE REAR DOOR,RIGHT SIDE ROCKER PANEL AND RIGHT SIDE REAR FENDER	New	1,000.00	600.00
3	RUST-PROOFING ON THE FRONT ACCIDENT AFFECTED	New	120.00	60.00
4	TO APPLY SILICON ONTO REAR WIND SCREEN	New	80.00	0.00
5	LABOUR FOR DISMANTLE & REFIX REAR WIND SCREEN	New	180.00	0.00
Gross Labour Cost (\$)			2,480.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >