

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21008249/T1UF3E2

Date: 08/11/2021

REFERENCE

Insured/Claimant:	MD HAIROMAN BIN MD SUM	Policy No:	1900004396	
Date of Loss:	01/08/2021	Nature of Claim:	OD	Claim No: 6589432272SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FK311Z	Engine No:	RC88E6302577
Make & Model:	HONDA XADV750, 745cc	Chassis No:	JH2RC95A4KK200866
Reg. Date:	10/01/2019 (Man. Year: 2018)	Odometer:	24729 km
Colour:	Silver		
Engine Capacity:	745 cc		
Market Value/New Car Price:	S\$24,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R17	Rear Tyre Size:	160/60 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,362.70	7,373.50	2,989.20	28.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	780.00	1,300.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,442.70	8,153.50	4,289.20	34.47
Approved Total (Overridden) (\$\$)		6,500.00		
- Excess (\$\$)	750.00	750.00	0.00	0.00
(\$\$)	11,692.70	5,750.00	5,942.70	50.82
+ GST 7.00/7.00% (\$\$)	818.49	402.50	415.99	50.82
Nett Amount (\$\$)	12,511.19	6,152.50	6,358.69	50.82

INSPECTION

Date of Assignment:	05/08/2021		
Date Inspected:	05/08/2021	Inspected At:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD Singapore 218216
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Cracked	385.00 FL	*385.00 FL
2	1		*FRONT RIGHT FORK ASSY	Not Necessary	1,388.00 FL	*- FL
3	1		*STEERING STEM	Not Necessary	485.00 FL	*- FL
4	2		*STEERING STEM BEARING	Not Necessary	90.00 FL	*- FL
5	1		*FRONT WHEEL AXLE	Bent	188.00 FL	*188.00 FL
6	1		*FRONT BRAKE DISK RIGHT	Bent	395.00 FL	*395.00 FL
7	1		*RIGHT REAR SIDE COVER	Cracked	450.00 FL	*450.00 FL
8	1		*RIGHT LOWER COVER	Not Necessary	375.00 FL	*- FL
9	1		*FRONT COVER NOSE	Cracked	199.00 FL	*199.00 FL
10	1		*RIGHT SIDE SILVER COVER	Cracked	185.00 FL	*185.00 FL
11	1		*RIGHT SIDE FAIRING ASSY UPPER	Cracked	495.00 FL	*495.00 FL
12	1		*RIGHT SIDE FAIRING BLACK COVER	Cracked	295.00 FL	*295.00 FL
13	1		*RIGHT REAR FOOTREST	Cut	115.00 FL	*115.00 FL
14	1		*STEERING HANDLE	Bent	305.00 FL	*305.00 FL
15	1		*RIGHT VIEW MIRROR	Broken	145.00 FL	*145.00 FL
16	1		*RIGHT FRONT SIGNAL ASSY	Cut	140.00 FL	*140.00 FL
17	1		*RIGHT HANDGUARD	Cut	185.00 FL	*185.00 FL
18	1		*RIGHT FLOORSTEP	Cut	305.00 FL	*305.00 FL
19	1		*RIGHT SKIRT	Cut	295.00 FL	*295.00 FL
20	1		*EXHAUST	Bent	1,105.00 FL	*1,105.00 FL
21	1		*EXHAUST PROTECTOR	Dented	198.00 FL	*198.00 FL
22	1		*FRONT SPORT RIM	Not Necessary	885.00 FS	*- FS
23	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
24	1		*TOP CASE	Cut	215.00 FS	*215.00 FS
25	1		*SET RIGHT SIDE SLIDER	Cut	235.00 FL	*235.00 FL
26	1		*ABS RIGHT DISK (Supplementary)	Bent	195.00 FL	*195.00 FL
27	1		*RIGHT SIDE BLACK LOWER COVER (Supplementary)	Deformed	325.00 FL	*325.00 FL
28	1		*HONDA EMBLEM (Supplementary)	Necessary	45.00 FL	*45.00 FL
29	1		*RIGHT FOOTREST RUBBER (Supplementary)	Torn	115.00 FL	*115.00 FL
30	1		*X ADV METAL (Supplementary)	Bent	205.00 FL	*205.00 FL
31	1		*HANDGUARD METAL (Supplementary)	Bent	145.00 FL	*145.00 FL
32	1		*METER ASSY (Supplementary)	Cracked	690.00 FL	*690.00 FL
33	1		*RIGHT FOOT REST HOLDER (Supplementary)	Deformed	305.00 FL	*305.00 FL
34	1		*NOSE LOWER (Supplementary)	Dented	115.00 FL	*115.00 FL
35	1		*HANDBRAKE COVER (Supplementary)	Cracked	155.00 FL	*155.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,388.00	8,165.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,025.30	791.50
Total Parts (S\$)	10,362.70	7,373.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	120.00	80.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM	New	700.00	450.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM	New	150.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES	New	180.00	0.00
6	SPRAY PAINTING	New	300.00	100.00
7	LABOUR FOR SUPPLEMENTARY ITEMS (Supplementary)	New	250.00	150.00
Gross Labour Cost (\$\$)			2,080.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >