9/28/21, 9:33 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG21008251/AVCN2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 Date: 28/09/2021

**REFERENCE** 

Insured/Claimant: HELM ASIA PTE LTD Policy No: 1900171992

Date of Loss: 10/04/2021 Nature of Claim: OD Claim No: 9949486884SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMQ160C

Make & Model: AUDI A6, 2.0 TFSI (A) Engine No: DLH065461

Reg. Date: 25/10/2019 (Man. Year: 2019) Chassis No: WAUZZZF21LN014116

Colour: Blue Odometer: 23420 km

Engine Capacity: 1984 cc
Market Value/New Car Price: \$\$167,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 245/45R19 Rear Tyre Size: 245/45R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,334.00	2,398.40	2,935.60	55.04
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,872.00	1,722.00	1,150.00	40.04
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,206.00	4,120.40	4,085.60	49.79
	- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
	(S\$)	6,606.00	2,520.40	4,085.60	61.85
	+ GST 7.00/7.00% (S\$)	462.42	176.43	285.99	61.85
	Nett Amount (S\$)	7,068.42	2,696.83	4,371.59	61.85

**INSPECTION** 

Date of Assignment: 05/08/2021

Date Inspected: 04/08/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,832.00 FS	*2,265.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	650.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE-LOWER CENTRE	Not Necessary	153.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER	Not Necessary	210.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	252.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	434.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	29.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	21.00 FS	*- FS
9	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	266.00 FS	*- FS
10	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	71.00 FS	*- FS
11	1		*FRONT WHEEL SPOILER-RH	Deformed	166.00 FS	*132.80 FS
12	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS
F=Fra	nchise	part. S=Spc	Nett.		,	
				Total Parts (S\$)	5,334.00	2,398.40
			Report was unsubmitted during this print-	out .	,	

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labou	r Cost (S\$)	2,872.00	1,722.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >