

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III19014858/EES3Q2-1  
**Date:** 30/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	PC5603Y	<b>Insured Vehicle No :</b>	SHB4053R
Date of Loss:	12/08/2019	Nature of Claim:	TP
		Claim No:	MCT19080224

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>PC5603Y</b>	Engine No:	ISB67E525022189649
Make & Model:	YUTONG ZK6107HE, 6.7 D (A)	Chassis No:	LZYTBD63G1041951
Reg. Date:	08/11/2016 (Man. Year: 2016)	Odometer:	113851 km
Colour:	Multi-colour		
Engine Capacity:	6690 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	11 R22.5	Rear Tyre Size:	11 R22.5
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,407.00	621.00	6,786.00	91.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	2,800.00	1,600.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,807.00</b>	<b>3,421.00</b>	<b>8,386.00</b>	<b>71.03</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		

(S\$)	11,807.00	2,700.00	9,107.00	77.13
<b>+ GST 7.00/7.00% (S\$)</b>	826.49	189.00	637.49	77.13
<b>Nett Amount (S\$)</b>	<b>12,633.49</b>	<b>2,889.00</b>	<b>9,744.49</b>	<b>77.13</b>
<b>+ Loss of Use (3.0 x S\$250.00/day) (S\$)</b>		750.00		
<b>(S\$)</b>		3,639.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,819.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,830.00</b>		

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 23/08/2019

Estimated Period of Repair: 4.0 days

Inspected At:

Feida Bus Consortium Pte Ltd (HQ)  
6 SUNGEI KADUT WAY  
Singapore 728786

**Adjuster:** CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Apr 2021)	
<b>Parts:</b>	N/A	YUTONG ZK6107HE 6.7 D (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC5603Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LEFT WHEEL ARCH PANEL	Dented	580.00 FL	*580.00 FL
2	1		*REAR LEFT ROCKER PANEL	Repair	620.00 FL	*- FL
3	1		*REAR LEFT LUGGAGE DOOR ASSY	Repair	3,500.00 FL	*- FL
4	1		*REAR LEFT LUGGAGE DOOR LOCK	Cut	110.00 FL	*110.00 FL
5	1		*REAR LEFT INSPECTION LID COVER ASSY	Repair	3,200.00 FL	*- FL
6	2		*REAR LEFT INSPECTION LID COVER LOCK	Not Necessary	220.00 FL	*- FL
					<b>Sub Total (S\$)</b>	<b>8,230.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>690.00</b>
					<b>Total Parts (S\$)</b>	<b>7,407.00</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY PAINTING ON REAR RIGHT WHEEL ARCH PANEL ,REAR RIGHT LUGGAGE REAR RIGHT INSPECTION LID COVER ,REAR BUMPER AND ALL AFFECTED ACCIDENT PART	New	2,900.00	1,800.00
2	TO KNOCK /STRAIGHTEN ALL NECESSARY PART INCLUDING REPAIRING AND CHANGING OF ALL DAMAGED PARTS AND ALIGN SAME	New	1,500.00	1,000.00
<b>Gross Labour Cost (S\$)</b>			<b>4,400.00</b>	<b>2,800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >