

ASS. REC. BY:

Stor

REF:

III

ASSIGNMENT

From:

Date:

23/8/19

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

PC 5603Y

at Workshop m/s

Feida Bus

of

No. 6 Sungai Kerdut way

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Iam (waiting)

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC5603Y

Yr Regn:

8/11/16

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yutong ZK610

c.c

6690

Colour

Multi - Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

113851

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

L2YTB TO 636194/951 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

11R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

12/8/19

D.O.I.

23/8/19

Survey held at

Feida Bus

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 145K

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

Lump Sum / I.B.I. (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

S + RS. SI

Photos

Others

TOTAL



Feida Bus Consortium Pte Ltd

06 Sungei Kadut Way Singapore 728786
Tel: +656655 6665 Fax: +656655 6665

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BY HAND ONLY

23 August 2019

To: INDIA INTERNATIONAL INSURANCE PTE LTD

c/o : Attending Surveyor

(+65 6225 6371)

Dear Sirs

THIRD PART CLAIM ;- REPAIR ESTIMATE FOR PC 5603 Y

Traffic accident on 12/08/2019 at about 1735 hours along Sungei Kadut Way involving PC 5603 Y and SJW180Z

We append below the repair estimate for PC 5603 D, MODEL : YUTONG ZK6107HE AUTO

Part required :-

1 pc	Rear right wheel arch panel	✓ MD	\$ 580.00
1 pc	Rear right rocker panel	✗ R	\$ 620.00
1 pc	Rear right luggage door assy.	✗ R	\$ 3500.00
1 pc	Rear right luggage door lock	✓ CVT	\$ 110.00
1 pc	Rear right inspection lid cover assy.	✗ R	\$ 3200.00
2 pcs	Rear left inspection lid cover lock	✗ NN	\$ 220.00
			\$ 8230.00
	Less 10% trade discount		\$ 823.00
	Total part cost		\$ 7407.00

Labour charges:-

To putty and spray painting on rear right wheel arch panel, rear right luggage rear right inspection lid cover, rear bumper and all affected accident part

\$ 2900 1800

To knock/straighten all necessary part including repairing and changing of all damaged parts and align same 350


\$ 1500 1000

Total repair cost

\$ 11807.00

Note:- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress, insurer and/or their surveyor will be notified accordingly.

Price quoted is subjected to 7% GST



Encl.

Steve (LKK)
8372 8813

W.L. Ng
23/8/19, 11-am
4 days
L/S - 20%
Ry Af Sky