

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21008257/R1QF3N2**Date:** 21/09/2021REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SKE1996M **Insured Vehicle No :** SLQ8808C

Date of Loss: 31/07/2021 Nature of Claim: TP Claim No: DMPC2100248H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE1996M**

Make & Model: PROTON EXORA A, 1.6 (A) Engine No: S4PHRT7475

Reg. Date: 15/02/2012 (Man. Year: 2012) Chassis No: PL1FZ6YRRCF079476

Colour: White Odometer: 107367 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,536.61	3,279.93	2,256.68	40.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,740.00	220.00	11.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,496.61	5,019.93	2,476.68	33.04
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	7,496.61	4,000.00	3,496.61	46.64
+ GST 7.00/7.00% (S\$)	524.76	280.00	244.76	46.64
Nett Amount (S\$)	8,021.37	4,280.00	3,741.37	46.64

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 16/08/2021 Inspected At: Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	M1-MPV	PROTON EXORA A 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE1996M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,210.70 FL	*1,210.70 FL
2	1		*REAR BOOT GARNISH	Serviceable	396.50 FL	*- FL
3	1		*REAR BOOT LOGO	Necessary	110.60 FL	*69.00 FL
4	1		*REAR BOOT EMBLEM EXORA	Necessary	120.00 FL	*45.00 FL
5	1		*REAR BOOT EMBLEM CPS	Necessary	96.30 FL	*55.00 FL
6	1		*REAR BOOT LOCK	Cut	117.00 FL	*117.00 FL
7	1		*REAR BOOT CATCH	Serviceable	65.00 FL	*- FL
8	1		*REAR BOOT RUBBER	Necessary	176.80 FL	*123.00 FL
9	1		*REAR WINDSCREEN MOULDING	Not Necessary	277.40 FL	*- FL
10	1		*REAR END PANEL	Bent	699.00 FL	*520.00 FL
11	1		*REAR END PANEL TRIM	Deformed	277.60 FL	*189.00 FL
12	1		*REAR BUMPER	Deformed	965.10 FL	*630.00 FL
13	1		*REAR BUMPER TOW COVER	Serviceable	48.00 FL	*- FL
14	2		*REAR BUMPER REFLECTOR L + R	Serviceable	158.00 FL	*- FL
15	1		*REAR BUMPER SPONGE	Serviceable	220.10 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Bent	479.20 FL	*325.00 FL
17	2		*REAR BUMPER LOWER BRACKET L + R	Serviceable	88.60 FL	*- FL
18	2		*REAR BUMPER RETAINER L + R	Serviceable	113.00 FL	*- FL
19	10		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
20	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FL	*- FL
21	2		*REAR CHASSIS MEMBER L + R (NPA)	Repair	0.00 FL	*- FL
22	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
23	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
24	1		*REAR BUMPER SENSOR	Not Working	280.00 FS	*200.00 FS
25	1		*REAR NUMBER PLATE	Cracked	60.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,102.90	3,612.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	566.29	332.77
Total Parts (\$\$)	5,536.61	3,279.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD REAR END PANEL.TO REPAIR REAR FLOOR PANEL,REAR FENDER L+R,REAR CHASSIS MEMBER.TO REMOVE & REFIX DAMAGED PARTS,STRAIGHTEN & REALIGN AFFECTED AREAS	New	700.00	600.00
2	TO SPRAY REAR BOOT,BOOT GARNISH,REAR PANEL.REAR FENDER PANEL,REAR BUMPER,REAR FENDER L+R AND AFFECTED AREAS	New	800.00	800.00
3	TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	180.00	120.00
4	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM	New	80.00	60.00
5	TO REMOVE & REFIX LAGGAGE COMPARTMENT,SIDE GARNISH,SIDE TRIM BOARD CARPET AND OTHER ATTACHMENT PARTS	New	80.00	60.00
6	TO INSTALL REVERSE SENSOR & WATER TEXT	New	60.00	60.00
7	TO RUST PROOF AFFECTED AREAS	New	60.00	40.00
Gross Labour Cost (\$\$)			1,960.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >