

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21008263/UVF3E2

Date: 24/08/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001508024

Claimant Vehicle No : SLD1840Y

Insured Vehicle No : XE1141J

Date of Loss: 02/08/2021

Nature of Claim: TP

Claim No: 260776

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD1840Y

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A)

Engine No: G4FGGU192985

Reg. Date: 07/06/2016 (Man. Year: 2016)

Chassis No: KMHD841CMHU199274

Colour: Red

Odometer: 108192 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 7 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,200.12	6,304.32	8,895.80	58.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,610.00	3,020.00	2,590.00	46.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,810.12	9,324.32	11,485.80	55.19
Approved Total (Overridden) (S\$)		7,400.00		
(S\$)	20,810.12	7,400.00	13,410.12	64.44
+ GST 7.00/7.00% (S\$)	1,456.71	518.00	938.71	64.44
Nett Amount (S\$)	22,266.83	7,918.00	14,348.83	64.44

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 06/08/2021 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2021)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1840Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Dented / Buckled	1,780.40 FL	*1,780.40 FL
2	1	*REAR BOOT LID INNER LOCK }	Twisted	185.70 FL	*117.00 FL
3	1	*REAR BOOT LID INNER LOCK COVER }		68.00 FL	*- FL
4	1	*REAR BOOT LID LATCH	Not Necessary	38.50 FL	*- FL
5	1	*REAR BOOT LID TRUCK SWITCH	Not Necessary	197.00 FL	*- FL
6	1	*REAR BOOT LID HINGES	N/S Bent	331.20 FL	*90.00 FL
7	2	*REAR BOOT LID STOPPERS	Not Necessary	24.00 FL	*- FL
8	1	*REAR BOOT LID WEATHERSTRIP	Twisted	298.20 FL	*95.00 FL
9	2	*REAR BOOT LID LAMP	Cracked	805.80 FL	*570.00 FL
10	1	*REAR BOOT LID INNER TRIM	Deformed / Torn	285.60 FL	*185.00 FL
11	2	*REAR NUM PLATE LAMP	Cracked	171.40 FL	*60.00 FL
12	2	*TAIL LAMP	Cracked	892.20 FL	*726.00 FL
13	2	*TAIL LAMP PANEL	Repair	1,046.20 FL	*- FL
14	1	*REAR BUMPER	Distorted	545.30 FL	*498.00 FL
15	1	*REAR BUMPER LOWER	Not Necessary	405.90 FL	*- FL
16	2	*REAR BUMPER MUDFLAP	Not Necessary	89.60 FL	*- FL
17	2	*REAR BUMPER REFLECTOR	Cracked	271.80 FL	*82.00 FL
18	2	*REAR BUMPER SIDE RETAINER	Bent	136.00 FL	*70.00 FL
19	1	*REAR BUMPER LOWER COVER - BIG LH	Not Necessary	205.60 FL	*- FL
20	1	*REAR BUMPER LOWER COVER - SMALL LH	Not Necessary	148.40 FL	*- FL
21	1	*REAR REINFORCEMENT	Not Necessary	394.80 FL	*- FL
22	2	*REAR REINFORCEMENT BRACKET - METAL	Not Necessary	397.60 FL	*- FL
23	2	*REAR REINFORCEMENT BRACKET - TOP	Twisted	76.00 FL	*50.00 FL
24	3	*REAR REINFORCEMENT BRACKET - BOTTOM	Not Necessary	114.00 FL	*- FL
25	1	*SMART KEY ANTENNA - INNER	Not Necessary	276.50 FL	*- FL
26	1	*SMART KEY ANTENNA - OUTER	Not Necessary	276.50 FL	*- FL
27	1	*END PANEL	Badly Dented	785.90 FL	*455.00 FL
28	1	*END PANEL TOP GARNISH	Twisted	215.60 FL	*60.00 FL
29	1	*SPARE TYRE PANEL	Repair	898.60 FL	*- FL
30	1	*SPARE TYRE PANEL RETAINER	Not Necessary	65.00 FL	*- FL
31	1	*SPARE TYRE TOP BOARD	Not Necessary	385.60 FL	*- FL
32	1	*REAR FENDER	N/S Buckled / O/S Repair	3,784.00 FL	*1,769.00 FL
33	1	*REAR FENDER FUEL LIP COVER	Not Necessary	165.00 FL	*- FL
34	2	*REAR FENDER AIR OUTLET VENT	Not Necessary	170.00 FL	*- FL
35	2	*REAR FENDER INNER COWLING	Not Necessary	404.60 FL	*- FL
36	1	*REAR FENDER INNER TRIM	N/S Deformed	577.40 FL	*208.00 FL
37	1	*SET REAR WINDSCREEN GLASS MOULDING	Necessary	180.00 FL	*65.00 FL
38	1	*REAR BOOT LID H LOGO	Necessary	85.00 FS	*40.00 FS
39	1	*REAR BOOT LID ELANTRA EMBLEM	Necessary	51.00 FS	*35.00 FS
40	1	*REAR BOOT LID GLS EMBLEM	Necessary	39.00 FS	*35.00 FS
41	1	*SET BOOT LID INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
42	1	*SET REAR CAMERA	Shorted	380.00 FS	*300.00 FS
43	1	*SET REAR NUMBER PLATE W CASING	Bent	70.00 FS	*40.00 FS
44	1	*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
45	1	*SET REVERSE SENSORS	Shorted	350.00 FS	*200.00 FS
46	1	*END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
48	1		*FLOOR PANEL INSULATOR PADS	Not Necessary	120.00 FS	*- FS
49	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
50	1		*REAR WINDSCREEN GLASS PRIMER & CLEANER	Necessary	60.00 FS	*30.00 FS
51	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
52	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$\$)	18,618.90	7,680.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,418.78	1,376.08	
	Total Parts (\$\$)	15,200.12	6,304.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT / STRAIGHTEN / REALIGN ACCIDENT AFFECTED AREAS	New	2,500.00	1,500.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	2,000.00	1,100.00
3	TO TUFF COAT ON AFFECTED AREAS	New	150.00	90.00
4	TO CONDUCT WIRING CHECK AND REPAIR	New	80.00	20.00
5	TO REMOVE / TRANSFER BOOTLID AND MECHANISM	New	180.00	60.00
6	TO REMOVE / REFIX REAR INTERIOR UPHOLSTERY, SEAT, SEAT BELT	New	200.00	80.00
7	TO REMOVE / REFIX REAR WINDSCREEN GLASS	New	200.00	120.00
8	TO REMOVE / REFIX REVERSE SENSOR AND DISTANCE SETTING }	New	150.00	50.00
9	TO REMOVE / REFIX REVERSE CAMERA }	New	150.00	0.00
Gross Labour Cost (\$\$)			5,610.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >