



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8411J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER COVER	DEFORMED	430.90	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET RH	CRACKED	28.00	28.00
1	RADIATOR GRILLE	NOT NECESSARY	1,409.10	-
1	FRT BUMPER MOULDING CENTRE UPPER	NOT NECESSARY	368.50	-
1	HEADLAMP RH	NOT NECESSARY	1,993.65	-
1	DAY LIGHT RH	NOT NECESSARY	642.50	-
1	FRT FENDER RH	BENT	588.80	588.80
1	FRT FENDER SHIELD RH	TORN	164.70	164.70
1	FRT WHEEL HUB CAP RH	CUT	346.40	346.40
1	EMBLEM-BLUE DRIVE RH	NECESSARY	26.60	26.60
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	949.30	-
1	FRT DOOR MIRROR ASSY RH	TO REPAIR SEE LABOUR	1,391.70	-
	LESS 20% DISCOUNT		-1,672.43	-321.48
			6,689.72	1,285.92
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR MIRROR ASSY RH.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		700.00	500.00
	CHECK WIRING.		60.00	30.00
			1,810.00	1,055.00
GRAND TOTAL			8,499.72	2,340.92

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,340.92
--	--	--	-----------------

Report Ref No. NS/INC21008264/T1ucn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.