



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200169

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/01/2022
Reference CC3/CTI21008267/Grs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1447Y
Insured Veh. GBK 9077M
Claim No. SNM21D204346/LKKDS
Policy No. DMCVSNW00008172100
Accident Date 04/08/2021
Inspection Date 06/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI21008267/Grs3q2	
			Date: 07/01/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 9077M	Veh. Inspected	SHD 1447Y	
Policy No.	DMCVSNW00008172100	Coverage (\$)	0.00	
Claim No.	SNM21D204346/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	06/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I30	c.c	1582	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	TMAD281UVHJ134122	Colour	SILVER	
Odometer	364447 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MAXXIS	6 mm	
L/H Front Tyre	195/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	195/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/08/2021	Inspection Date	06/08/2021	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1447Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BROKEN	811.11	811.11
1	FRONT BUMPER EMBLEM	NOT NECESSARY	27.80	-
2	FRONT BUMPER N/S & O/S SIDE BRACKET @\$32.51	O/S CUT / N/S NOT NECESSARY	65.02	32.51
1	FRONT BUMPER O/S UPPER BRACKET	NOT NECESSARY	92.60	-
1	FRONT BUMPER O/S SUPPORT BRACKET	NOT NECESSARY	37.01	-
1	FRONT BUMPER O/S FOG LIGHT GARNISH	SCRATCHED	25.00	25.00
1	SUPPORT PANEL	NOT NECESSARY	1,292.20	-
1	FRONT O/S HEAD LAMP	CRACKED	1,531.57	1,531.57
1	FRONT O/S FENDER	BUCKLED	514.02	514.02
1	FRONT O/S FENDER INNER SHIELD	DEFORMED	176.72	176.72
1	FRONT O/S FENDER SIGNAL LAMP	NOT NECESSARY	32.10	-
1	O/S MIRROR ASSY	NOT NECESSARY	742.49	-
1	FRONT O/S DOOR QUADRANT MOULDING	NOT NECESSARY	11.70	-
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	1,723.60	-
2	FRONT O/S HINGES @\$36.10	NOT NECESSARY	72.20	-
1	WASHER TANK	NOT NECESSARY	51.40	-
1	WASHER TANK MOTOR	NOT NECESSARY	75.00	-
1	FRONT O/S MUD FLAP	NOT NECESSARY	47.45	-
1	FRONT O/S RIM	CUT	246.00	246.00
1	FRONT O/S LOWER ARM	NOT NECESSARY	811.34	-
1	FRONT O/S SHOCK ABSORBER	NOT NECESSARY	611.56	-
1	FRONT O/S TIE ROD END	NOT NECESSARY	72.50	-
1	FRONT O/S BALL JOINT	NOT NECESSARY	91.90	-
1	FRONT O/S KNUCKLE ARM	NOT NECESSARY	873.88	-
1	FRONT O/S KNUCKLE BEARING	NOT NECESSARY	349.60	-
1	FRONT O/S STABILIZER LINK	NOT NECESSARY	88.50	-
	LESS 10% DISCOUNT		-2,094.85	-667.39
			8,379.42	2,669.54

Report Ref No. CC3/CTI21008267/Grs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT O/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SET O/S DOOR STICKERS (SN)	NECESSARY	100.00	100.00
1	16 TYRE (TYRE BRAND:MAXXIS) (SN)	SCRATCHED	200.00	80.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			456.00	286.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK FRONT O/S WHEEL ALIGNMENT.		80.00	60.00
	TO ADJUST /FOCUS FRONT N/S & O/S HEAD LAMPS.		80.00	20.00
	TO DISMANTLE /REFIT THE FRONT O/S UNDERCARRIAGE.	NOT NECESSARY	250.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO DISMANTLE & REFIT THE INNER COMPONENTS OF THE FRONT O/S DOOR INTO THE NEW SHELL DOOR.	NOT NECESSARY	150.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE O/S ROCKER PANEL ETC.INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR .		900.00	540.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT O/S FENDER ,FRONT O/S DOOR ,FRONT O/S WINDSCREEN PILLAR ,O/S ROCKER PANEL,O/S SIDE MIRROR .		1,200.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
			3,040.00	1,260.00
	GRAND TOTAL		11,875.42	4,215.54



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,350.00
---	--	--	----------

Report Ref No. CC3/CTI21008267/Grs3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1447Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 1447Y

RE-INSPECTION

