

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21008271/EVCE2

**Date:** 13/09/2021

### REFERENCE

|                              |                                               |                             |                    |           |                         |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|-----------|-------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00068922000 |           |                         |
| <b>Claimant Vehicle No :</b> | SLQ8769G                                      | <b>Insured Vehicle No :</b> | YQ976Z             |           |                         |
| Date of Loss:                | 11/07/2021                                    | Nature of Claim:            | TP                 | Claim No: | SNM21D204130/C02/THAMYL |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SLQ8769G                     | Engine No:  | G4FGCU467185      |
| Make & Model:               | HYUNDAI ELANTRA, 1.6 (A)     | Chassis No: | KMHDH41CMCU423563 |
| Reg. Date:                  | 16/02/2012 (Man. Year: 2012) | Odometer:   | 0 km              |
| Colour:                     | Silver                       |             |                   |
| Engine Capacity:            | 1591 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 205/55 R16   | Rear Tyre Size:  | 205/55 R16   |
| Front Left Side:  | Pirelli 4 mm | Rear Left Side:  | Pirelli 4 mm |
| Front Right Side: | Pirelli 4 mm | Rear Right Side: | Pirelli 4 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                            | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                     | 26,184.00        | 6,653.60        | 19,530.40        | 74.59        |
| Miscellaneous Items                       | 0.00             | 0.00            | 0.00             |              |
| Labour                                    | 5,200.00         | 2,420.00        | 2,780.00         | 53.46        |
| Paintwork Labour                          | 0.00             | 0.00            | 0.00             |              |
| Towing                                    | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>31,384.00</b> | <b>9,073.60</b> | <b>22,310.40</b> | <b>71.09</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                  | <b>5,000.00</b> |                  |              |
| <b>Nett Amount (\$\$)</b>                 | <b>31,384.00</b> | <b>5,000.00</b> | <b>26,384.00</b> | <b>84.07</b> |

### INSPECTION

|                             |                          |                                                                                                 |
|-----------------------------|--------------------------|-------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 05/08/2021               |                                                                                                 |
| Date Inspected:             | 06/08/2021 Inspected At: | Auburn Auto Pte Ltd (HQ)<br>176 SIN MING DRIVE, #04-18 SIN MING<br>AUTOCARE<br>Singapore 575721 |
| Estimated Period of Repair: | 14.0 days                |                                                                                                 |

**Adjuster:** CHEN TSUE YEE

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 10 Sep 2021)             |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLQ8769G)                                                                                                                                    |                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                           |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's | Amount       |
|-----|-----|----------|-------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *REVERSE SENSOR               | Broken        | 200.00 F   | *200.00 FL   |
| 2   | 1   |          | *MISSING SCREWS & NUTS        | Not Necessary | 250.00 F   | *- FL        |
| 3   | 1   |          | *RIGHT TAIL LIGHT BRACKET     | Not Necessary | 120.00 F   | *- FL        |
| 4   | 1   |          | *END PANEL GARNISH            | Not Necessary | 250.00 F   | *- FL        |
| 5   | 1   |          | *TAIL LAMP LOWER BRACKET      | Not Necessary | 120.00 F   | *- FL        |
| 6   | 1   |          | *REAR RIGHT BUMPER RETAINER   | Broken        | 250.00 F   | *45.00 FL    |
| 7   | 1   |          | *REAR RIGHT TAILLIGHT BRACKET | Not Necessary | 220.00 F   | *- FL        |
| 8   | 1   |          | *REAR LEFT TAILLIGHT BRACKET  | Not Necessary | 220.00 F   | *- FL        |
| 9   | 1   |          | *REAR RIGHT DOOR BODY LINING  | Not Necessary | 300.00 F   | *- FL        |
| 10  | 1   |          | *REAR RIMS AND TYRE (LH)      | Cut           | 500.00 F   | *450.00 FL   |
| 11  | 1   |          | *REAR RIGHT WHEEL BEARING     | Not Necessary | 200.00 F   | *- FL        |
| 12  | 1   |          | *REAR LEFT WHEEL BEARING      | Necessary     | 200.00 F   | *200.00 FL   |
| 13  | 1   |          | *REAR RIGHT DOOR BODY LINING  | Not Necessary | 320.00 F   | *- FL        |
| 14  | 1   |          | *SPARE TYRE BOARD             | Not Necessary | 250.00 F   | *- FL        |
| 15  | 1   |          | *REAR CUSHION SEAT LOCK       | Not Necessary | 200.00 F   | *- FL        |
| 16  | 1   |          | *BOOTLID WEATHERSTRIP         | Crushed       | 180.00 F   | *180.00 FL   |
| 17  | 1   |          | *FAULTY WIRING                | Not Necessary | 550.00 F   | *- FL        |
| 18  | 1   |          | *REAR RIGHT BOOT MUDGUARD     | Repair        | 120.00 F   | *- FL        |
| 19  | 1   |          | *REAR LEFT BOOT MUDGUARD      | Dented        | 1,603.00 F | *1,603.00 FL |
| 20  | 1   |          | *BUMPER BRACKET               | Not Necessary | 1,200.00 F | *- FL        |
| 21  | 1   |          | *REAR RIGHT ABSORBER          | Not Necessary | 750.00 F   | *- FL        |
| 22  | 1   |          | *REAR LEFT ABSORBER           | Not Necessary | 750.00 F   | *- FL        |
| 23  | 1   |          | *REAR RIGHT MUDGUARD          | Not Necessary | 120.00 F   | *- FL        |
| 24  | 1   |          | *REAR LEFT MUDGUARD           | Torn          | 120.00 F   | *120.00 FL   |
| 25  | 1   |          | *LEFT BOOTLID LAMP            | Cut           | 250.00 F   | *196.00 FL   |
| 26  | 1   |          | *RIGHT BOOTLID LAMP           | Cut           | 250.00 F   | *196.00 FL   |
| 27  | 1   |          | *LEFT TAIL LIGHT              | Missing       | 362.00 F   | *362.00 FL   |
| 28  | 1   |          | *RIGHT TAIL LIGHT             | Broken        | 362.00 F   | *362.00 FL   |
| 29  | 1   |          | *BOOT LOCK                    | Bent          | 150.00 F   | *116.00 FL   |
| 30  | 1   |          | *REAR UNDERCARRIAGE (AXLE)    | Bent          | 1,500.00 F | *1,388.00 FL |
| 31  | 1   |          | *BOOT LID                     | Dented        | 907.00 F   | *907.00 FL   |
| 32  | 1   |          | *SPARE TYRE WELL              | Not Necessary | 250.00 F   | *- FL        |
| 33  | 1   |          | *BOOT INTERIOR LINING         | Not Necessary | 500.00 F   | *- FL        |
| 34  | 1   |          | *REAR BUMPER                  | Broken        | 2,000.00 F | *486.00 FL   |
| 35  | 1   |          | *END PANEL                    | Repair        | 2,000.00 F | *- FL        |
| 36  | 1   |          | *BUMPER CLIP RIGHT            | Necessary     | 150.00 F   | *30.00 FL    |
| 37  | 1   |          | *BUMPER CLIP LEFT             | Not Necessary | 150.00 F   | *- FL        |
| 38  | 1   |          | *BUMPER STRIP                 | Not Necessary | 200.00 F   | *- FL        |
| 39  | 1   |          | *FRONT RIGHT RIM              | Not Necessary | 200.00 F   | *- FL        |
| 40  | 1   |          | *REAR LEFT DOOR SPEAKER       | Not Necessary | 250.00 F   | *- FL        |
| 41  | 1   |          | *RIGHT SIDE FENDER            | Not Necessary | 250.00 F   | *- FL        |
| 42  | 1   |          | *UNDER TRAY COVER             | Not Necessary | 350.00 F   | *- FL        |
| 43  | 1   |          | *RIM TYRE                     | Not Necessary | 360.00 F   | *- FL        |
| 44  | 1   |          | *RIGHT HEADLIGHT              | Not Necessary | 400.00 F   | *- FL        |
| 45  | 1   |          | *CONDENSER                    | Not Necessary | 450.00 F   | *- FL        |
| 46  | 1   |          | *RADIATOR                     | Not Necessary | 450.00 F   | *- FL        |

| No.                                              | Qty | Part No. | Particulars               | Condition     | Repairer's | Amount       |
|--------------------------------------------------|-----|----------|---------------------------|---------------|------------|--------------|
| 47                                               | 1   |          | *REINFORCEMENT BAR SPONGE | Not Necessary | 450.00 F   | *- FL        |
| 48                                               | 1   |          | *REAR LEFT DOOR REPLACE   | Dented        | 5,000.00 F | *1,476.00 FL |
| F=Franchise part. L=ListItemDisc.                |     |          |                           |               |            |              |
| Sub Total (\$)                                   |     |          |                           |               | 26,184.00  | 8,317.00     |
| - List Item Discount on L Items 0.00/20.00% (\$) |     |          |                           |               | 0.00       | 1,663.40     |
| Total Parts (\$)                                 |     |          |                           |               | 26,184.00  | 6,653.60     |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                             | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                         |          |                 |                 |
| 1                               | TOW                                                                                                                     | New      | 200.00          | 80.00           |
| 2                               | CHECKING OF WIRING, LIGHTING AND RESETTNG                                                                               | New      | 300.00          | 30.00           |
| 3                               | REMOVE AND REFIT REAR UNDERCARRIAGE                                                                                     | New      | 500.00          | 200.00          |
| 4                               | WHEEL ALIGNMENT                                                                                                         | New      | 100.00          | 60.00           |
| 5                               | REMOVE AND REPLACE DAMAGED PARTS                                                                                        | New      | 800.00          | 0.00            |
| 6                               | APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL                                                                       | New      | 800.00          | 50.00           |
| 7                               | WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIRS INCLUDING CUT AND WIELD, REALIGN BODY STRUCTURE                   | New      | 1,500.00        | 1,000.00        |
| 8                               | RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT | New      | 1,000.00        | 1,000.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                         |          | <b>5,200.00</b> | <b>2,420.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >