

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008274/AEA3Q2**Date:** 17/05/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLH6189R	Insured Vehicle No :	SLV2015L
Date of Loss:	05/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003330

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH6189R		
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Engine No:	L15B3539028
Reg. Date:	11/11/2016 (Man. Year: 2016)	Chassis No:	GK81007711
Colour:	White	Odometer:	54805 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,186.32	6,161.68	7,024.64	53.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	1,990.00	2,050.00	50.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,226.32	8,151.68	9,074.64	52.68
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	17,226.32	6,500.00	10,726.32	62.27
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		7,177.45		

INSPECTION

Date of Assignment:	05/08/2021		
Date Inspected:	06/08/2021	Inspected At:	Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Apr 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH6189R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER INNER COWLING RH	Torn	187.20 FL	*187.20 FL
2	1		*FRONT FENDER RH	Dented	645.20 FL	*645.20 FL
3	2		*FRONT FENDER INNER PANEL RH	Buckled	523.80 FL	*523.80 FL
4	1		*FRONT SIDESKIRT RH	Not Necessary	752.30 FL	*- FL
5	1		*FRONT HEADLAMP RH	Cracked	2,250.80 FL	*2,250.80 FL
6	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	185.30 FL	*- FL
7	1		*FRONT BUMPER	Distorted	1,185.30 FL	*1,050.00 FL
8	1		*FRONT BUMPER SIDE RETAINER	Damaged	95.20 FL	*45.00 FL
9	1		*FRONT BUMPER TOW COVER	Missing	82.90 FL	*42.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Dented	698.30 FL	*297.00 FL
11	1		*FRONT FOGLAMP RH	Not Necessary	245.80 FL	*- FL
12	1		*FRONT FOGLAMP COVER RH TOP	Cracked	125.90 FL	*125.90 FL
13	1		*FRONT FOGLAMP COVER RH BOTTOM	Cracked	135.80 FL	*135.80 FL
14	1		*FRONT LOWER GRILLE	Deformed	245.80 FL	*141.00 FL
15	1		*FRONT BUMPER LOWER COVER	Torn	198.50 FL	*198.50 FL
16	1		*FRONT RADIATOR GRILLE BASE	Not Necessary	468.30 FL	*- FL
17	1		*FRONT RADIATOR GRILLE CHROME	Not Necessary	398.20 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Not Necessary	782.90 FL	*- FL
19	1		*FRONT BONNET INNER LOCK BRACKET	Not Necessary	158.20 FL	*- FL
20	2		*FRONT RADIATOR AIR GUIDE	Not Necessary	397.20 FL	*- FL
21	1		*FRONT AIRCON PIPE	Not Necessary	245.80 FL	*- FL
22	1		*FRONT CONDENSER	Not Necessary	985.30 FL	*- FL
23	1		*FRONT WASHER TANK	Cracked	198.60 FL	*198.60 FL
24	1		*FRONT WASHER TANK MOTOR	Not Necessary	125.30 FL	*- FL
25	1		*FRONT RH LOWER ARM	Bent	428.60 FL	*428.60 FL
26	1		*FRONT RH SHOCK ABSORBER	Bent	485.20 FL	*485.20 FL
27	1		*FRONT RH KNUCKLE ARM	Not Necessary	582.30 FL	*- FL
28	1		*FRONT WHEEL HUB BEARING RH	Damaged	428.20 FL	*185.00 FL
29	1		*FRONT TIE ROD RH	Not Necessary	185.60 FL	*- FL
30	1		*FRONT ANTI ROLL BAR LINKAGE RH	Not Necessary	152.80 FL	*- FL
31	1		*FRONT ANTI ROLL BAR	Not Necessary	852.30 FL	*- FL
32	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
33	1		*SET FRONT GRILLE CLIPS	Not Necessary	30.00 FS	*- FS
34	1		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
35	1		*SET FRONT TYRE RH	Cut	350.00 FS	*150.00 FS
36	1		*SET FRONT RIM RH	Cut	1,200.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,072.90	7,549.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,886.58	1,387.92
Total Parts (\$\$)	13,186.32	6,161.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT /WELD AND REALIGN PARTS	New	1,800.00	800.00
2	SPRAY PAINTING	New	1,600.00	800.00
3	ANTI RUST	New	120.00	80.00
4	WIRING CHECK ON HEADLAMP /FOCUSSING	New	120.00	30.00
5	TO REMOVE /REPLACE FRONT UNDERCARRIAGE	New	280.00	200.00
6	COMPUTERISED WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			4,040.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >