



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WBA7T22040CE38095

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	USED FRONT FENDER RIGHT	BENT	300.00	300.00
1	USED FRONT HEADLAMP RIGHT	MISSING	900.00	900.00
1	USED FRONT BUMPER	MISSING	480.00	480.00
4	FRONT BUMPER SUPPORT BRACKETS @\$22.00	MISSING	88.00	88.00
1	USED FRONT GRILL	MISSING	250.00	250.00
1	USED FRONT WHEEL ARC	MISSING	80.00	80.00
1	USED FRONT BONNET	BENT	400.00	400.00
1	IMPACT ABSORBER	MISSING	81.00	81.00
			2,579.00	2,579.00
	<b><u>LABOUR</u></b>			
	TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, BONNET, RIGHT FENDER).		500.00	500.00
	TO INSTALL FRONT RIGHT HEAD LAMP. }		50.00	30.00
	TO CHECK WIRING. }		70.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		100.00	50.00
	TO RESPRAY ALL REPLACED AND AFFECTED PARTS.		850.00	660.00
			1,570.00	1,240.00
<b>GRAND TOTAL</b>			<b>4,149.00</b>	<b>3,819.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,819.00</b>

Report Ref No. CS/TP21008281/Kuce2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.