

ASS. REC. BY:

REF:

TP / CS/TP21008281/Kuc

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: WBA7T22040CE38095

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

38095

Yr Regn:

1

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW

740Li

c.c

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

5880

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA7T22040CE38095

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R20

R:

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

P

mm

D.O.A.

1/1

D.O.I.

30/7/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

For LTA purpose, will contact Bryan for inspection after repair.
No repair days; no need Simon audit.

26/8/2021 Submit final fig \$3819. (RED \$330; 8%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 26/8 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

Fees

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ \$3819

leading the way...

Scanned with CamScanner



Labour

Submit By : BRYAN TAN
Year of Manufacture 2020

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any