



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. W1K2173872A050176

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	USED FRONT FENDER LEFT	BENT	300.00	300.00
1	USED FRONT BUMPER	BENT	600.00	600.00
1	USED REAR BUMPER	CRACKED	550.00	550.00
4	FRONT BUMPER SUPPORT BRACKETS @\$22.06	NECESSARY	88.24	88.24
1	USED REAR TAIL LAMPS OUTER	BROKEN	200.00	200.00
1	USED FRONT LEFT HEAD LAMPS	MISSING	750.00	750.00
1	FRT LH SURROUND GARNISH	BROKEN	350.00	350.00
1	FRT LH HEADLAMP SUPPORT	CRACKED	240.00	240.00
1	FRT LH FENDER INNER GARNISH	CRACKED	180.00	180.00
1	REAR BUMPER DIFFUSER	CRACKED	270.00	270.00
			3,528.24	3,528.24
	<u>LABOUR</u>			
	TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, FRONT BUMPER, LEFT FENDER). }		500.00	500.00
	TO INSTALL REAR TAIL LAMPS OUTER. }		70.00	-
	TO CHECK ELECTRICAL WIRING FOR WHOLE CAR.		100.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		100.00	60.00
	TO RESPRAY ON AFFECTED PARTS.		1,100.00	1,000.00
			1,870.00	1,620.00
	GRAND TOTAL		5,398.24	5,148.24
	RECOMMENDED COST OF REPAIRS			5,148.24

Report Ref No. CS/TP21008282/Kqce2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.