



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WBSJF02090CE60106

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	USED FRONT FENDER RIGHT	BENT	250.00	250.00
1	SET USED FRONT BUMPER	BROKEN	350.00	350.00
4	FRONT BUMPER SUPPORT BRACKETS @\$20.00	CRACKED	80.00	80.00
1	USED FRONT GRILL	CRACKED	150.00	150.00
2	USED FRONT WHEEL ARC LEFT AND RIGHT @\$65.00	CRACKED	130.00	130.00
1	USED FRONT BONNET	BUCKLED	250.00	250.00
1	IMPACT ABSORBER	BENT	58.00	58.00
2	USED SIDE RADIATOR @\$150.00	BENT	300.00	300.00
1	USED CENTRE RADIATOR	BENT	250.00	250.00
4	PARKING SENSORS @\$60.00	MISSING	240.00	240.00
1	USED BMW HEAD LAMP LH (LED)	CRACKED	350.00	350.00
1	USED BMW HEAD LAMP RH (LED)	CRACKED	350.00	350.00
1	HEAD LAMP BRACKET LH	CRACKED	95.00	95.00
1	HEAD LAMP BRACKET RH	CRACKED	95.00	95.00
1	LEFT ENGINE HOOD HINGE	DISTORTED	35.00	35.00
1	LEFT ENGINE HOOD HINGE	DISTORTED	35.00	35.00
1	LEFT TENSION STRUT WITH RUBBER MOUNTING	BENT	180.00	180.00
1	RIGHT TENSION STRUT WITH RUBBER MOUNTING	BENT	180.00	180.00
1	WISHBONE, BOTTOM, WITH RUBBER MOUNT LEFT	BENT	200.00	200.00
1	WISHBONE, BOTTOM, WITH RUBBER MOUNT RIGHT	BENT	200.00	200.00
1	USED BMW FRONT AXLE SUPPORT	BENT	350.00	350.00
1	HEAD LAMP BRACKET LH	CRACKED	85.00	85.00
1	HEAD LAMP BRACKET RH	CRACKED	85.00	85.00
			4,298.00	4,298.00
<b><u>LABOUR</u></b>				
TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, FRONT BUMPER, BONNET).			600.00	600.00
TO INSTALL DAMAGED PARTS OF FRONT WHEELS UNDERCARRIAGE.			800.00	400.00
TO INSTALL FRONT HEADLAMPS.			100.00	40.00

Report Ref No. CS/TP21008283/Kqce2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	50.00
	RESPRAY ON AFFECTED PARTS.		1,500.00	1,200.00
	WHEEL ALIGNMENT.		120.00	120.00
			3,240.00	2,410.00
GRAND TOTAL			7,538.00	6,708.00
RECOMMENDED COST OF REPAIRS				6,708.00

Report Ref No. CS/TP21008283/Kqce2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.