

ASS. REQ. BY:

REF:

CS/TP21008283/Kqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 60106 Yr Regn: 1Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW M5 cc _____Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBS JF02090CE 60106Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NI / S/Rlm / STD A/Rlm orTyre Size: F: 275/35ZR20R: 285/35ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PRT SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 1/1 D.O.I. 23/6/2021

Survey held at _____

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 For LTA purpose; No repair days; no need Simon audit.

06/08/21 Submit final fig \$6708 (Red 830, 11%)

Date/Time, File Pass to?

☐: Prell. Report

1) 06/08 Typist

☐: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech Invs (\$ _____)☐: Weekend (\$ _____)

Report Format: TP

Lump Sum / I.B.I. (\$) 6708

Not Authair



No.176 Sin Ming Drive, #04-05 Autocare, Singapore 575721
Tel: 6452 5515 Fax: 6452 5595

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

TBA

BMW M5 COMPETITION PACKAGE AUTO
WBSJF02090CE60106

Submit By :
Year Manufacture :
Engine No. :

BRYAN TAN

2020

23043657

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Used Front Fender Right <i>R1</i>	1	\$250.00	\$250.00	✓
2	Used Front Bumper Set <i>B2</i>	1	\$350.00	\$350.00	✓
3	Front Bumper Support Brackets <i>CM</i>	4	\$20.00	\$80.00	✓
4	Used Front Grill <i>CM</i>	1	\$150.00	\$150.00	✓
5	Used Front Wheel Arc Left and Right <i>CM</i>	2	\$65.00	\$130.00	✓
6	Used Front Bonnet <i>B2</i>	1	\$250.00	\$250.00	✓
7	Impact Absorber <i>R1</i>	1	\$58.00	\$58.00	✓
8	Used Side Radiator <i>R1</i>	2	\$150.00	\$300.00	✓
9	Used Centre Radiator <i>R1</i>	1	\$250.00	\$250.00	✓
10	Parking Sensors <i>A17</i>	4	\$60.00	\$240.00	✓
11	USED BMW HEAD LAMP LH (LED) <i>CM</i>	1	\$350.00	\$350.00	✓
12	USED BMW HEAD LAMP RH (LED) <i>CM</i>	1	\$350.00	\$350.00	✓
13	HEAD LAMP BRACKET LH <i>CM</i>	1	\$95.00	\$95.00	✓
14	HEAD LAMP BRACKET RH <i>CM</i>	1	\$95.00	\$95.00	✓
15	LEFT ENGINE HOOD HINGE <i>M17</i>	1	\$35.00	\$35.00	✓
16	LEFT ENGINE HOOD HINGE <i>O17</i>	1	\$35.00	\$35.00	✓
17	LEFT TENSION STRUT WITH RUBBER MOUNTING <i>R1</i>	1	\$180.00	\$180.00	✓
18	RIGHT TENSION STRUT WITH RUBBER MOUNTING <i>R1</i>	1	\$180.00	\$180.00	✓
19	WISHBONE, BOTTOM, WITH RUBBER MOUNT LEFT <i>R1</i>	1	\$200.00	\$200.00	✓
20	WISHBONE, BOTTOM, WITH RUBBER MOUNT RIGHT <i>R1</i>	1	\$200.00	\$200.00	✓
21	USED BMW FRONT AXLE SUPPORT <i>R1</i>	1	\$350.00	\$350.00	✓
22	HEAD LAMP BRACKET LH <i>CM</i>	1	\$85.00	\$85.00	✓
23	HEAD LAMP BRACKET RH <i>CM</i>	1	\$85.00	\$85.00	✓
				\$4,298.00	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



No.176 Sin Ming Drive, #04-05 Autocare, Singapore 575721

Labour

Vehicle No. : TBA Submit By : BRYAN TAN
Make & Model : BMW M5 COMPETITION PACKAGE AUTO Year of Manufacture : 2020

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quoted accordingly as a supplementary.

Date: