

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SCH 9939E. 2018 July.

Mercedes Benz E200 1991cc

TP AXA

Veron

WDD 2130422A456279.

Rear Bumper torn

1615 ✓

Rear Bumper Clips. ^{new}

50(SN) ✓

Rear Bumper Side Holder. RH. ^{new}

130. X

Rear RH Fender Repair ^{new}

2325 +

Rear RH Fender Inner Shield. ^{new}

249 +

Rear RH Fender Inner Shield Clips. ^{new}

30(SN) +

Rear RH Wheel Rim. ^{new}

~~1250~~ 800(SN)

Rear RH Tyre ^{new}

380(SN). +

Rear RH Door Dented

2337 ✓

Rear RH Door Lock ^{new}

385 +

Rear RH Door Weatherstripe. ^{new}

259 ✓

Rear Windscreen Moulding ^{new}

254 +

Rear Windscreen Sealant ^{new}

60(SN) +

SCH 9939 E.

Rear RH Lower Arm.	}	661 +
Rear RH Stuy Arm.		248 +
Rear RH Knuckle Arm.		Not 1488 +
Rear RH Wheel Hub clw Bearing.		Nec 385 +
Rear RH Shock Absorbers.		489. +

4211

S.W. 850

3789.90

Panel Beating

Spray Painting.

Wiring.

1500

To spray full coat

To remove reverse sensor

To transfer rear door fittings.

To remove rear undercarriage

To perform wheel alignment.

~~1400~~ 600.

~~1200~~ 800.

~~50~~ 30

~~150~~ 60.

~~100~~ 50

~~150~~ 80

380 +

~~150~~ 80

16,185.00

total 6139.90

2/5: 4.9K

0.5 Days