

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008298/AEA3Q2**Date:** 06/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100155158
Claimant Vehicle No :	GN903M	Insured Vehicle No :	SJS2099J
Date of Loss:	03/08/2021	Nature of Claim:	TP
		Claim No:	4016351908SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GN903M	Engine No:	4JJ1272636
Make & Model:	ISUZU NHR85AUE4A, 3.0 D (M)	Chassis No:	JAANHR85EC7100112
Reg. Date:	28/05/2013 (Man. Year: 2012)	Odometer:	142670 km
Colour:	Blue		
Engine Capacity:	2999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	GREEN-MAX 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,634.53	5,392.78	3,241.75	37.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	2,150.00	820.00	27.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,604.53	7,542.78	4,061.75	35.00
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	11,604.53	6,000.00	5,604.53	48.30
+ GST 7.00/7.00% (S\$)	812.32	420.00	392.32	48.30
Nett Amount (S\$)	12,416.85	6,420.00	5,996.85	48.30
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
Nett Liability (S\$)		7,420.00		

INSPECTION

Date of Assignment:	05/08/2021	
Date Inspected:	05/08/2021	Inspected At: J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT PANEL	Dented	862.00 FL	*862.00 FL
2	1		*ISUZU EMBLEM	Necessary	118.00 FL	*118.00 FL
3	1		*FRT W/SCREEN GLASS	Not Necessary	1,458.00 FL	*- FL
4	1		*FRT W/SCREEN MOULDING	Necessary	214.00 FL	*214.00 FL
5	1		*FRT RH CORNER PANEL	Dented	194.00 FL	*194.00 FL
6	1		*FRT RH WING MIRROR	Not Necessary	151.00 FL	*- FL
7	1		*FRT RH WING MIRROR BRACKET	Not Necessary	238.00 FL	*- FL
8	2		*HEADLAMP	Cracked	1,032.00 FL	*1,032.00 FL
9	1		*FRT RH HEADLAMP RUBBER	Missing	18.00 FL	*18.00 FL
10	1		*FRT SIGNAL LAMP	O/S Cracked	310.00 FL	*155.00 FL
11	1		*FRT GRILLE	Cracked	386.00 FL	*386.00 FL
12	6		*FRT GRILLE CLIPS	Necessary	30.00 FL	*30.00 FL
13	1		*FRT BUMPER	Distorted	577.00 FL	*577.00 FL
14	2		*FRT BUMPER BRACKET	Bent	194.00 FL	*194.00 FL
15	1		*AIR CON BLOWER	Cracked	638.00 FL	*638.00 FL
16	1		*AIR CON BLOWER COIL W/HEATER	Cracked	1,599.00 FL	*1,233.00 FL
17	1		*FRT RH DOOR	Repair	827.00 FL	*- FL
18	1		*FRT PANEL CO LOGO	Necessary	300.00 FS	*100.00 FS
19	1		*FRT W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
20	1		*ERP BRACKET	Not Necessary	26.00 FS	*- FS
21	1		*FRT NO PLATE	Bent	30.00 FS	*30.00 FS
22	1		*BODY STICKER	Necessary	30.00 FS	*30.00 FS
23	1		*FRT RH DOOR CO LOGO	Necessary	500.00 FS	*200.00 FS
24	1		*FRT RH STEP GARNISH	Cracked	211.10 FL	*211.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,993.10	6,272.10
- List Item Discount on L Items 15.00/15.00% (S\$)	1,358.57	879.32
Total Parts (S\$)	8,634.53	5,392.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	900.00
3	WIRING	New	30.00	30.00
4	REMOVE & REFIT FRT W/SCREEN	New	120.00	120.00
5	REMOVE & REFIT DASHBOARD	New	300.00	220.00
6	TOP UP GAS	New	120.00	80.00
Gross Labour Cost (\$\$)			2,970.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >