

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008300/APS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100502980-04
Claimant Vehicle No :	SMZ2256A	Insured Vehicle No :	GBE6608H
Date of Loss:	04/08/2021	Nature of Claim:	TP
		Claim No:	5123017025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ2256A		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	LEB6747314
Reg. Date:	16/04/2021 (Man. Year: 2018)	Chassis No:	RU31327302
Colour:	Black	Odometer:	6110 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,299.52	5,520.40	6,779.12	55.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,220.00	2,070.00	4,150.00	66.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,519.52	7,590.40	10,929.12	59.01
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	18,519.52	6,000.00	12,519.52	67.60
+ GST 7.00/7.00% (S\$)	1,296.37	420.00	876.37	67.60
Nett Amount (S\$)	19,815.89	6,420.00	13,395.89	67.60
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,876.45		
Global Sum Settlement (S\$)		6,850.00		

INSPECTION

Date of Assignment:	06/08/2021		
Date Inspected:	10/08/2021	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	o/s Cracked	640.00 FL	*320.00 FL
2	2		*REAR FENDER COWLING	Not Necessary	300.40 FL	*- FL
3	2		*REAR FENDER ARCED GARNISH	Not Necessary	369.40 FL	*- FL
4	1		*REAR BUMPER	Deformed	777.00 FL	*777.00 FL
5	1		*REAR BUMPER REFLECTOR	O/S Cracked	302.20 FL	*151.10 FL
6	1		*REAR BUMPER SIDE	O/S Torn	460.00 FL	*230.00 FL
7	2		*REAR BUMPER SIDE RETAINER	Necessary	114.00 FL	*114.00 FL
8	1		*TAIL LAMP	O/S Cut	950.00 FL	*475.00 FL
9	1		*TAILGATE	Distorted	1,101.00 FL	*1,101.00 FL
10	1		*TAILGATE REVERSE CAMERA	Not Necessary	1,020.00 FL	*- FL
11	1		*TAILGATE LOGO	Not Necessary	65.00 FL	*- FL
12	1		*TAILGATE EMBLEM VEZEL	Necessary	69.00 FL	*69.00 FL
13	1		*TAILGATE EMBLEM HYBRID	Necessary	75.00 FL	*75.00 FL
14	1		*TAILGATE OUTER GARNISH	Not Necessary	396.00 FL	*- FL
15	1		*TAILGATE OUTER MOULDING	Cut	210.00 FL	*210.00 FL
16	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	112.00 FL	*- FL
17	1		*TAILGATE SIDE LAMP	O/S Cut	728.00 FL	*364.00 FL
18	2		*TAILGATE DAMPER	Not Necessary	302.00 FL	*- FL
19	1		*TAILGATE INNER HOLDER	Not Necessary	52.00 FL	*- FL
20	2		*TAILGATE STOPPER	Not Necessary	38.00 FL	*- FL
21	1		*TAILGATE TOP LOCK	Damaged	145.00 FL	*145.00 FL
22	1		*TAILGATE OUTER SWITCH BUTTOM	Not Necessary	290.00 FL	*- FL
23	1		*TAILGATE LOWER LOCK	Not Necessary	24.70 FL	*- FL
24	1		*TAILGATE INNER TRIM	Cracked	398.60 FL	*398.60 FL
25	1		*TAILGATE LOCK CONNECTOR	Not Necessary	217.00 FL	*- FL
26	1		*TAILGATE WEATHERSTRIP	Cut	168.40 FL	*168.40 FL
27	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	134.00 FL	*134.00 FL
28	1		*BUZZER	Cracked	109.00 FL	*109.00 FL
29	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
30	1		*REAR END PANEL TOP GARNISH	Cracked	121.00 FL	*121.00 FL
31	1		*REAR FLOOR PANEL BOTTOM GARNISH	Deformed	269.00 FL	*269.00 FL
32	1		*REAR FLOOR PANEL TOP BOARD	Deformed	300.40 FL	*300.40 FL
33	1		*REAR STORAGE BOX	Cracked	495.00 FL	*264.00 FL
34	1		*REAR EXHAUST BOX	Not Necessary	980.00 FL	*- FL
35	4		*REAR EXHAUST MOULDING	Not Necessary	72.00 FL	*- FL
36	2		*REAR EXHAUST GASKET	Not Necessary	120.00 FL	*- FL
37	1		*HYBRID FAN ASSY	Not Necessary	416.00 FL	*- FL
38	1		*HYBRID DUCT ASSY AIR INTAKE	Not Necessary	100.80 FL	*- FL
39	1		*HYBRID DUCT ASSY IPU INTAKE	Not Necessary	187.20 FL	*- FL
40	1		*HYBRID COVER COMP IPU	Not fitted	182.50 FL	*- FL
41	1		*HYBRID FAN ASSY REAR	Not Necessary	170.30 FL	*- FL
42	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
43	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
44	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	60.00 FS	*- FS
45	1		*SET TAILGATE INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
46	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
47	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
48	1		*SET TAIL LAMP CLIP	Necessary	40.00 FS	*10.00 FS
49	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	60.00 FS	*30.00 FS
50	1		*SET REAR FENDER COWLING CLIP	Not Necessary	60.00 FS	*- FS
51	1		*SET REAR FENDER ARCED GARNISH CLIP	Not Necessary	60.00 FS	*- FS
52	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
53	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
54	1		*SET REAR FLOOR PANEL BOTTOM GARNISH CLIP	Necessary	60.00 FS	*30.00 FS
55	1		*REAR EXHAUST CHROME PIPE (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	15,001.90
					2,702.38	6,785.50
					- List Item Discount on L Items 20.00/20.00% (\$)	1,265.10
					Total Parts (\$)	5,520.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX VIDEO RECORDER	New	80.00	50.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
12	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESER MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
13	REMOVE AND REFIX AND REPROGRAMMING HYBRID SYSTEM	New	850.00	0.00
Gross Labour Cost (\$\$)			6,220.00	2,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >