

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21008303/ETF3E2

Date: 10/09/2021

REFERENCE

Insured/Claimant: SYED MUHAMMAD FARID BIN SYED YUSOF
SHAH

Policy No: MPC21P00082300

Date of Loss: 05/08/2021

Nature of
Claim:

OD

Claim
No:

DMPC2100252H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJG9064B**

Make & Model: HONDA STREAM, 1.8 L (A)

Engine No: R18A12804307

Reg. Date: 19/07/2008 (Man. Year: 2008)

Chassis No: JHMRN68408S204308

Colour: Blue

Odometer: 200825 km

Engine Capacity: 1799 cc

Market Value/New Car Price: S\$41,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: KAPSEN 4 mm

Rear Left Side:

KAPSEN 4 mm

Front Right Side: KAPSEN 4 mm

Rear Right Side:

KAPSEN 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,581.00	3,603.60	5,977.40	62.39
Miscellaneous Items	140.00	50.00	90.00	64.29
Labour	1,900.00	1,200.00	700.00	36.84
Paintwork Labour	1,200.00	1,000.00	200.00	16.67
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,821.00	5,853.60	6,967.40	54.34
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	12,821.00	4,650.00	8,171.00	63.73
+ GST 7.00/7.00% (S\$)	897.47	325.50	571.97	63.73
Nett Amount (S\$)	13,718.47	4,975.50	8,742.97	63.73

INSPECTION

Date of Assignment: 06/08/2021 Present Location:

Accord Auto Services Pte Ltd (HQ)

Accord Auto Services Pte Ltd (HQ)

Date Inspected: 06/08/2021 Inspected At:

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2021)
Parts: M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJG9064B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN (WCP)	Not Necessary	900.00 F	*- F
2	1		*FRONT WINDSCREEN MOULDING (WCP)	Not Necessary	40.00 F	*- F
3	1		*FRONT BONNET (WCP)	Dented	450.00 F	*450.00 F
4	1		*FRONT BONNET INSULATOR (WCP)	Crushed	120.00 F	*120.00 F
5	1		*FRONT BONNET LOCK (WCP)	Bent	80.00 F	*80.00 F
6	2		*FRONT BONNET HINGE (WCP)	Bent	110.00 F	*110.00 F
7	2		*FRONT BONNET STOPPER (WCP)	Not Necessary	16.00 F	*- F
8	1		*FRONT BONNET STAND (WCP)	Not Necessary	18.00 F	*- F
9	1		*FRONT BONNET STAND CLIP (WCP)	Not Necessary	5.00 F	*- F
10	1		*FRONT BONNET RUBBER/SEAL (WCP)	Not Necessary	80.00 F	*- F
11	1		*FRONT GRILLE BASE (WCP)	Broken	130.00 F	*130.00 F
12	1		*FRONT GRILLE CHROME (WCP)	Cut	160.00 F	*160.00 F
13	1		*FRONT GRILLE LOGO (WCP)	Necessary	30.00 F	*30.00 F
14	1		*FRONT LOWER GRILLE (WCP)	Not Necessary	80.00 F	*- F
15	1		*FRONT BUMPER (WCP)	Broken	360.00 F	*360.00 F
16	2		*FRONT BUMPER SIDE RETAINER (WCP)	Broken	40.00 F	*40.00 F
17	2		*FRONT BUMPER FOGLAMP GARNISH (WCP)	Not Necessary	170.00 F	*- F
18	1		*FRONT REINFORCEMENT BAR (WCP)	Not Necessary	180.00 F	*- F
19	1		*FRONT SUPPORT PANEL (WCP) }	Dented	320.00 F	*320.00 F
20	1		*FRONT SUPPORT TOP COVER/GARNISH (WCP)	Broken	85.00 F	*85.00 F
21	1		*FRONT RH HEADLAMP (WCP)	Broken	620.00 F	*620.00 F
22	1		*FRONT RH HEADLAMP TOP PANEL (WCP) }	Not Necessary	65.00 F	*- F
23	1		*FRONT RH HEADLAMP LOWER BRACKET (WCP)	Broken	28.00 F	*28.00 F
24	1		*FRONT RH FENDER (WCP)	Dented	350.00 F	*350.00 F
25	1		*FRONT RH FENDER SIGNAL LIGHT (WCP)	Broken	28.00 F	*28.00 F
26	1		*FRONT RH FENDER SHIELD (WCP)	Not Necessary	70.00 F	*- F
27	1		*FRONT RH FENDER INNER PANEL TOP (WCP)	Not Necessary	500.00 F	*- F

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT RH FENDER INNER PANEL CENTRE (WCP)	Not Necessary	320.00 F	*- F
29	1		*FRONT RH ABSORBER WHEEL HUB (WCP)	Not Necessary	580.00 F	*- F
30	1		*ENGINE MOUNTING SET (WCP)	Not Necessary	450.00 F	*- F
31	1		*WASHER TANK,NECK & CAP (WCP)	Crushed	85.00 F	*85.00 F
32	1		*AIRCON CPNDENSER (WCP)	Not Necessary	520.00 F	*- F
33	1		*AIRCON CPNDENSER DISCHARGE PIPE (WCP)	Bent	280.00 F	*280.00 F
34	1		*RADIATOR (WCP)	Not Necessary	600.00 F	*- F
35	2		*RADIATOR TOP STOPPER (WCP)	Not Necessary	20.00 F	*- F
36	1		*RADIATOR FAN COWLING ASSY (WCP)	Not Necessary	250.00 F	*- F
37	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	90.00 F	*- F
38	2		*RADIATOR LOWER STOPPER (WCP)	Not Necessary	20.00 F	*- F
39	1		*RADIATOR LOWER STOPPER ALTERNATOR (WCP)	Not Necessary	400.00 F	*- F
40	1		*BELTING (WCP)	Not Necessary	60.00 F	*- F

F=Franchise part.

Sub Total (\$)	8,710.00	3,276.00
+ Margin on L,N Items 10.00/10.00% (\$)	871.00	327.60
Total Parts (\$)	9,581.00	3,603.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT BUMPER, FRONT BONNET INSULATOR,FRONT FENDER SHIELD & UNDER BUMPER/ENGINE COVER CLIPS (NECESSARY)	100.00	50.00
2	1	WINDSCREEN SEALANT (NOT NECESSARY)	40.00	0.00
			Sub Total (\$\$)	140.00
				50.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Spray Painting to All Affected Areas	New	1,200.00	1,000.00
Labour Items				
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	New	1,000.00	950.00
3	Check Wiring System & Light	New	80.00	30.00
4	To Check & Adjust Wheel Aligment	New	80.00	0.00
5	To Remove/Refix Front Rh UnderCarriage To Facilities Repair	New	180.00	0.00
6	To Adjust Front Main Chassis	New	280.00	100.00
7	To Remove / Refix Air-con Condensor & Radiator (Top up Gas, Pipe & Etc...)	New	180.00	120.00
8	To Remove/Replace Windscreen	New	100.00	0.00
			Gross Labour Cost (\$\$)	3,100.00
				2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >