5/17/23, 2:57 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21008316/KYA3Q2

Date: 17/05/2023

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210015370

Claimant Vehicle No: SMS2698U Insured Vehicle No: GBH4637X

Date of Loss: 06/08/2021 Nature of Claim: TP Claim No: 7794246333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS2698U

Make & Model: TOYOTA WISH, 1.8 CVT (A) Engine No: 2ZR1836654

Reg. Date: 22/09/2016 (Man. Year: 2016) Chassis No: JTDGG20W40J005299

Colour: Metallic Silver Odometer: 56590 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Goodyear 2 mm Rear Left Side: Goodyear 3 mm
Front Right Side: Goodyear 2 mm Rear Right Side: Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,822.27	4,053.30	768.97	15.95
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,800.00	1,450.00	350.00	19.44
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,622.27	5,503.30	1,118.97	16.90
	Approved Total (Overridden) (S\$)		4,400.00		
	Nett Amount (S\$)	6,622.27	4,400.00	2,222.27	33.56
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 06/08/2021

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 10/08/2021 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: HENRY NG KOK HUA

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Mtg Cracked	601.90 FL	*565.80 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	69.40 FL	*69.40 FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	365.20 FL	*- FL
4	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
5	1		*FRONT BUMPER SPONGE	Serviceable	101.90 FL	*- FL
6	1		*BONNET	Bent	977.80 FL	*787.00 FL
7	1		*BONNET LOGO	Necessary	72.20 FL	*72.20 FL
8	1		*BONNET LH HINGE	Repair	68.90 FL	*- FL
9	1		*FRONT LH FENDER	Buckled	896.90 FL	*689.20 FL
10	1		*FRONT GRILLE	Cracked	446.30 FL	*391.60 FL
11	2		*HEADLAMP (O/S)	Cracked	2,531.40 FL	*2,531.40 FL
12	1		*FRONT WIPER GARNISH LH EXTENSION	Missing	36.80 FL	*36.80 FL
13 F=Fra	1 Inchise	nart S=Snch	*FRONT DOOR OUTER MLDG Nett. L=ListItemDisc.	Necessary	180.00 FS	*180.00 FS
		part. O Opor	tott. 2 Elettering iss.	Sub Total (S\$)	6,369.70	5,344.40
	- List Item Discount on L Items 25.00/25.00% (S\$)				1,547.43	1,291.10
				Total Parts (S\$)	4,822.27	4,053.30
			Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT BUMPER ASSY ,FOG LAMPS ,GRILLE ,BONNET & ATTACHMENT ,FRT LH FENDER ,RADIATOR & FAN MOTOR ,TO STRAIGHTEN ,KNOCK & REPAIR FRT SUPPORT PANE & REALIGN THE SAME	New L	700.00	550.00
2	REMOVE AND REFIX AIRCON ,CHECK,VACUUM & REFILL GAS	New	100.00	0.00
3	PUTTY & RESPRAY ON FRT LH FENDER ,FRT LH DOOR ,FRT BUMPER ,REINFORCEMENT ,FRT SUPPORT PANEL ,BONNET	New	1,000.00	900.00
	Gross Lab	our Cost (S\$)	1,800.00	1,450.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >