

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21008320/KEA3Q2
Date: 29/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHC5931U	Insured Vehicle No :	SFW1441L
Date of Loss:	04/08/2021	Nature of Claim:	TP
		Claim No:	7344784706SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5931U		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002616
Reg. Date:	06/03/2015 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC281484
Colour:	Metallic White/Red	Odometer:	706978 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,415.81	0.00	3,415.81	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	500.00	7,080.00	93.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,995.81	500.00	10,495.81	95.45
+ GST 7.00/7.00% (S\$)	769.71	35.00	734.71	95.45

Nett Amount (S\$)	11,765.52	535.00	11,230.52	95.45
		+ Car Rental (1.0 x S\$96.99/day) (S\$)	96.99	
		+ Doc/Search Fee (S\$)	7.49	
		Nett Liability (S\$)	639.48	

INSPECTION

Date of Assignment: 05/08/2021

Date Inspected: 05/08/2021

Estimated Period of Repair: 1.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Repair	747.20 FL	*- FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
4	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
5	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
6	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
7	1		*FENDER PANEL FRT RH	Repair	437.10 FL	*- FL
8	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
9	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
10	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
11	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
12	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
13	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
14	1		*BUMPER CLIP FRT	Not Necessary	85.00 FS	*- FS
15	1		*FENDER CLIP	Not Necessary	65.00 FS	*- FS
16	1		*FENDER LINER CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,761.68	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	345.87	0.00
Total Parts (\$\$)	3,415.81	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (\$\$)			7,580.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >