

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21008322/GEA3Q2**Date:** 11/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070119721
<b>Claimant Vehicle No :</b>	SHB1798U	<b>Insured Vehicle No :</b>	SJD6621D
Date of Loss:	30/07/2021	Nature of Claim:	TP
		Claim No:	0130101808SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB1798U</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6157728
Reg. Date:	19/09/2014 (Man. Year: 2014)	Chassis No:	JTDKN36UX05750188
Colour:	Maroon	Odometer:	636378 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,334.00	618.23	2,715.77	81.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,094.00	430.00	1,664.00	79.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,428.00</b>	<b>1,048.23</b>	<b>4,379.77</b>	<b>80.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,428.00</b>	<b>900.00</b>	<b>4,528.00</b>	<b>83.42</b>
<b>+ Car Rental (4.5 x S\$104.86/day) (S\$)</b>		471.87		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>1,378.87</b>		

INSPECTION

Date of Assignment:	02/08/2021	
Date Inspected:	02/08/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Deformed	94.80 F	*71.10 F
2	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Deformed	94.80 F	*71.10 F
3	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
4	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
5	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
6	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
7	1		*END PANEL	Not Necessary	602.10 F	*- F
8	1		*UNDER COVER SUBASSY RR FLOOR	Not Necessary	514.50 F	*- F
9	1		*BUMPER SEAL ,RR RH	Not Necessary	65.70 F	*- F
10	1		*BUMPER SEAL ,RR LH	Not Necessary	88.90 F	*- F
11	1		*BUMPER LIP REAR	Not Necessary	228.90 F	*- F
12	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
13	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F
14	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
15	1		*ANTENNA ,ELECTRICAL LOWER REAR	Not Necessary	157.40 F	*- F
16	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	139.60 F	*- F
17	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	139.60 F	*- F
18	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F

F=Franchise part.

**Total Parts (S\$)**      **3,334.00**      **618.23**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	738.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
6	TO REMOVE AND REFIT WIRE HARDESS	New	200.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,094.00</b>	<b>430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >