

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008323/AES3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100427494
Claimant Vehicle No :	SLM8953L	Insured Vehicle No :	SKV1588T
Date of Loss:	06/08/2021	Nature of Claim:	TP
		Claim No:	0584340264SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM8953L		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	1ZZ3164548
Reg. Date:	12/11/2008 (Man. Year: 2008)	Chassis No:	JTDER12W203001023
Colour:	Bronze	Odometer:	277382 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Rotalla 6 mm	Rear Left Side:	Rotalla 6 mm
Front Right Side:	Rotalla 6 mm	Rear Right Side:	Rotalla 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,425.50	3,577.17	3,848.33	51.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	2,000.00	1,180.00	37.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,605.50	5,577.17	5,028.33	47.41
Approved Total (Overridden) (S\$)		4,400.00		

Nett Amount (\$)	10,605.50	4,400.00	6,205.50	58.51
+ Loss of Use (6.0 x \$100.00/day) (\$)		600.00		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		5,007.45		

INSPECTION

Date of Assignment: 07/08/2021

Date Inspected: 07/08/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Ysk Auto Workshop (HQ)
No.1 Kaki Bukit Avenue 6, #01-49 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	564.30 F	*564.30 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	2		*REAR BUMPER SIDE HOLDER	Necessary	130.20 F	*130.20 FL
4	1		*REAR BUMPER IMPACT BRACKET	O/S Dented	136.80 F	*68.40 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	156.00 F	*- FL
6	1		*REAR END PANEL	Dented	645.20 F	*645.20 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	245.20 F	*245.20 FL
8	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
9	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
10	1		*TAILLAMP	O/S Cracked	816.00 F	*408.00 FL
11	2		*TAILLAMP LOWER BRACKET	Not Necessary	83.40 F	*- FL
12	1		*TAILGATE	Dented	1,272.00 F	*1,272.00 FL
13	1		*TAILGATE LOCK	Damaged	363.40 F	*363.40 FL
14	1		*TAILGATE WEATHERSTRIPE	Cut	299.10 F	*299.10 FL
15	1		*TAILGATE GLASS MOULDING	Necessary	246.00 F	*246.00 FL
16	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
17	1		*TOYOTA LOGO	Necessary	61.10 F	*61.10 FL
18	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	1,381.00 F	*- FL
19	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
20	1		*FLOOR PANEL TOP BOARD	Not Necessary	535.80 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,425.50	4,652.90
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	1,075.73
Total Parts (S\$)	7,425.50	3,577.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (S\$)			3,180.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >