

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 7198K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,399.70	-
1	TAILLAMP BRACKET RH	BENT	258.60	119.00
1	TAILLAMP BRACKET LH	BENT	258.60	119.00
1	TAILLAMP ASSY RH	CUT	245.60	245.60
1	TAILLAMP ASSY LH	BROKEN	245.60	245.60
1	EXHAUST ASSY	BENT	1,856.20	485.00
1	NO PLATE BRACKET	BENT	250.40	127.00
1	REAR CHASSIS LH	TO REPAIR SEE LABOUR	958.50	-
2	REAR PARKING SENSOR	CUT (1 PC ONLY)	640.00	200.00
	LESS 25% DISCOUNT		-1,528.30	-385.30
			4,584.90	1,155.90
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN)	BENT	40.00	30.00
1	REAR STEP PANEL ASSY (SN)	BENT	1,500.00	400.00
			1,540.00	430.00
	<u>LABOUR</u>			
	LABOUR.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR CHASSIS LH.		800.00	600.00
	SPRAYPAINTING.		800.00	400.00
	ANTI-RUST COATING AND APPLY CORROSION PROTECTION.		200.00	30.00
			1,800.00	1,030.00
	GRAND TOTAL		7,924.90	2,615.90

RECOMMENDED COST OF LUMP SUM REPAIRS		2,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR21008326/Euf3n2



CHEN TSUE YEE

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator