

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008327/BQC2**Date:** 22/12/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00166192003

**Claimant Vehicle
No :** SMV3587J**Insured Vehicle
No :** SJA9922G

Date of Loss: 06/08/2021

Nature of Claim: TP

Claim
No: SNM21D204387/C2/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMV3587J**

Make & Model: TOYOTA VIOS, 1.5 (A)

Engine No: 2NR5428646

Reg. Date: 28/09/2020 (Man. Year: 2020)

Chassis No: MR2B23F3701201421

Colour: Black

Odometer: 9226 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size: 185/60R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,488.12	6,851.85	2,636.27	27.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,500.00	1,380.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,368.12	8,351.85	4,016.27	32.47
Approved Total (Overridden) (\$\$)		6,000.00		
(\$\$)	12,368.12	6,000.00	6,368.12	51.49
+ GST 7.00/7.00% (\$\$)	865.77	420.00	445.77	51.49
Nett Amount (\$\$)	13,233.89	6,420.00	6,813.89	51.49

INSPECTION

Date of Assignment: 18/11/2021

Date Inspected: 11/08/2021 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2021)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3587J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	540.00 FL	*540.00 FL
2	1		*BONNET LH HINGE	Not Damaged	57.00 FL	*- FL
3	1		*BONNET RH HINGE	Not Damaged	57.00 FL	*- FL
4	1		*BONNET INNER HEAT INSULATOR	Not Damaged	224.70 FL	*- FL
5	1		*BONNET LOCK	Not Damaged	112.50 FL	*- FL
6	1		*FRONT BUMPER	Broken	486.10 FL	*486.10 FL
7	1		*FRONT BUMPER RH SIDE RETAINER	Necessary	100.40 FL	*65.20 FL
8	1		*FRONT BUMPER LH SIDE RETAINER	Necessary	100.40 FL	*65.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	399.50 FL	*399.50 FL
10	1		*FRONT BUMPER LH FOG LAMP ASSY	Broken	355.00 FL	*355.00 FL
11	1		*FRONT BUMPER LH FOG LAMP COVER	Broken	75.20 FL	*75.20 FL
12	1		*FRONT BUMPER CENTRE GRILLE	Broken	37.50 FL	*37.50 FL
13	1		*FRONT BUMPER LOWER GRILLE	Broken	269.50 FL	*161.40 FL
14	1		*FRONT GRILLE	Broken	239.80 FL	*239.80 FL
15	1		*FRONT GRILLE LH SIDE MOULDING	Broken	51.20 FL	*51.20 FL
16	1		*FRONT GRILLE EMBLEM	Not Damaged	58.40 FL	*- FL
17	1		*FRONT GRILLE EMBLEM OUTER COVER	Not Damaged	75.10 FL	*- FL
18	1		*FRONT GRILLE TOP RUBBER SEAL	Not Damaged	24.60 FL	*- FL
19	1		*FRONT LH FENDER	Dented	427.50 FL	*427.50 FL
20	1		*FRONT LH FENDER SPLASH SHIELD	Torn	222.80 FL	*171.20 FL
21	1		*LH HEADLAMP ASSY	Broken	1,144.90 FL	*1,144.90 FL
22	1		*SUPPORT PANEL	Dented	1,162.00 FL	*891.00 FL
23	1		*AIRCON CONDENSER	Bent	1,133.20 FL	*1,133.20 FL
24	1		*RADIATOR ASSY	Bent	1,717.60 FL	*1,627.00 FL
25	1		*FRONT LH SHOCK ABSORBER	Not Damaged	421.90 FL	*- FL
26	1		*FRONT LH LOWER ARM	Not Damaged	505.30 FL	*- FL
27	1		*FRONT LH KNUCKLE ARM	Not Damaged	555.20 FL	*- FL
28	1		*FRONT LH WHEEL BEARING	Not Damaged	498.30 FL	*- FL
29	1		*SET BONNET INNER HEAT INSULATOR CLIPS	Not Necessary	70.00 FS	*- FS
30	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS
31	1		*SET FRONT LH FENDER SPLASH SHIELD	Necessary	70.00 FS	*30.00 FS
32	1		*RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS
33	1		*BRAKE FLUID	Not Necessary	70.00 FS	*- FS
34	1		*RH HEADLAMP ASSY	Broken	1,144.90 FL	*1,144.90 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,537.50	9,105.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,049.38	2,253.95
Total Parts (\$\$)	9,488.12	6,851.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS.TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	600.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	70.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER AND PIPES TO ASSIST REPAIR.REPAIR AIRCON GAS	New	200.00	100.00
6	REMOVE AND REPLACE RADIATOR ASSY,HOSES AND FAN ASSY TO ASSIST REPAIR.REFILL COOLANT	New	200.00	100.00
7	REMOVE AND REPLACE FRONT LH UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	280.00	0.00
8	REFOCUS AND ADJUST HEADLAMPS ASSY	New	50.00	0.00
Gross Labour Cost (\$\$)			2,880.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >